

BRIDGE NO.00848

77830 - UNION
ROUTE 89
over
INTERSTATE 84

Routine Inspection

10/10/2023

Inspected by: TranSystems



TABLE OF CONTENTS

<u>Section</u>	<u>Page Number</u>
Report Title Page	1
Location Map	2
In-Depth Components	3
Structure Inventory and Appraisal (BRI-19)	4
Inventory Routes Under (BRI-25)	9
Inspection Data (BRI-18)	10
National Bridge Elements	17
Rocker Bearing Measurements (BRI-15)	18
Fracture Critical Data (BRI-12)	20
Sketches	21
Pictures	34
Highway Bridge Work Items	54

Bridge No. 00848, Route 89 over Interstate-84, Union, CT

Inspected By: TranSystems Corporation Date: 10/13/2023



Professional Certification: I hereby certify that this report, including all of its contents, has been approved by me, and that I am a duly licensed professional engineer under the laws of the State of Connecticut.

Signature: *Richard C. Van Allen*


License No.: *16495*

Date: *11-3-2023*

Form: Location
Inspection type: Routine
Inspection Date: 10/10/2023
Inspected by: TranSystems

:Bridge No 00848

Town: UNION
Carried: ROUTE 89
Crossed: INTERSTATE 84
Inventory Route: Non-NHS



Location Map # 1

In-Depth Components

Bridge: 00848

Town: 77830 - UNION



Carried: ROUTE 89

Crossed: INTERSTATE 84

In-Depth - 1

Component: Concrete Deck

Comments: Span 1 and 2 deck, deck overhangs and outside face of parapets over the roadway.
100% of suspect areas and 25% of areas over roadway showing no apparent deterioration.

Access Requirements: Traffic control and bucket truck is needed.

Last Inspected: 10/18/2021 Frequency: 120 Inspection Due Date: 10/18/2031

In-Depth - 2

Component: Steel Multi-Girders

Comments: Bottom base plates for previous OHSS 21635 welded to web of girder 1 in span 1 in tension zone (>4"L longitudinal welds; fatigue category E), otherwise not inspected hands-on over 120- month cycle.

Access Requirements: Traffic control and bucket truck is needed.

Last Inspected: 10/18/2021 Frequency: 120 Inspection Due Date: 10/18/2031

In-Depth - 3

Component: Steel Expansion Bearings

Comments: Measurements of all lines of steel expansion bearings for spans greater than 50 feet shall be taken and recorded on the appropriate sheet in Chapter 6 of the BIM.

Access Requirements: Traffic control and bucket truck is needed.

Last Inspected: 10/18/2021 Frequency: 120 Inspection Due Date: 10/18/2031

Form: BRI-19, Rev. 2/15
Inspection type: Routine
Inspection Date: 10/10/2023
Inspected by: TranSystems

:Bridge No 00848

Town: UNION
Carried: ROUTE 89
Crossed: INTERSTATE 84
Inventory Route: Non-NHS

STRUCTURE INVENTORY & APPRAISAL

INSPECTION

Structurally Deficient Functionally Obsolete
Sufficiency Rating
(90) Inspection Date (91) Frequency
Indepth Insp Proposed next Indepth Year
Deck Survey Date Class
Access Flagman

	Frequency	Date	Type
Fracture	<input type="text"/>	<input type="text"/>	<input type="text"/>
Underwater	<input type="text"/>	<input type="text"/>	<input type="text"/>
Special	<input type="text"/>	<input type="text"/>	<input type="text" value="D Lateral movements of beams / supports"/>

IDENTIFICATION

Bridge Name
Town Code - Name
(5) Inventory Route
(A) Record Type
(B) Signing Prefix
(C) Level of Service
(D) Route Number.
(E) Dir Suffix
(6A) Featured Intersected
(6B) Critical Facility Indicator
(7) Facility Carried
(9) Location
(11) Mile Post Miles
(16) Latitude Deg. Min. Sec.
(17) Longitude Deg. Min. Sec.
(98) Border Bridge
(A) State Code (B) Percent Responsibility %
(C) Border Town Name
(99) Border Bridge Structure No.

STRUCTURE TYPE & MATERIALS

(43) Structure Type, Main
A) Material
B) Design Type
(44) Structure Type, Approach
A) Material
B) Design Type
(45) Number of Spans, Main Unit
(46) Number of Approach Spans
(107) Deck Structure Type
(108) Wearing Surface/Protection Systems
A) Type of Wearing Surface
B) Type of Membrane
C) Type of Deck Protection
Substructure
A) Material
B) Design Type
Paint
Type
Year
Comment

GEOMETRIC DATA

(48) Length of Maximum Span ft.
(49) Structure Length ft.
(50) Curb or Sidewalk Widths
A) Left ft. in. B) Right ft. in.
(51) Bridge Roadway Width Curb to Curb ft. in.
(52) Deck Width, Out to Out ft. in.
(32) Approach Roadway Width ft.

Form: BRI-19, Rev. 2/15
Inspection type: Routine
Inspection Date: 10/10/2023
Inspected by: TranSystems

:Bridge No 00848

Town: UNION
Carried: ROUTE 89
Crossed: INTERSTATE 84
Inventory Route: Non-NHS

(33) Bridge Median

Deck Area sq. ft.

(34) Skew Angle deg.

(35) Structure Flared

(10) Inv. Rte. Min. Vert. Clearance ft. in.

(47) Inv. Rte. Total Horiz. Clr. ft. in.

Log Inv. Rte. Total Horiz. Clr. ft. in.

RLog Inv. Rte. Total Horiz. Clr. ft. in.

(53) Min. Vert. Clearance Over Bridge ft. in.

(54) Log-Min. Vert. Underclearance ref. ft. in.

(55) Min. Lat Underclearance on Right ref. ft. in.

(56) Min. Lat Underclearance on Left ft. in.

CONDITION

(58) Deck

(59) Superstructure

(60) Substructure

(61) Channel & Channel Protections

(62) Culverts

(36) Traffic Safety Features

A) Bridge Railings

B) Transitions

C) Approach Guardrail

D) Approach Guardrail Ends

WATERWAY

Drainage Basin Waterway

(38) Navigation Control

(39) Navigation Vertical Clearance ft.

(40) Navigation Horiz. Clr. ft.

(111) Pier/Abutment Navigation

(116) Vert-Lift Brg Nav Min ft. in.

AGE AND SERVICE

Year Built (106) Year Reconstructed

(42) Type of Service

A) On

B) Under

(28) Number of Lanes

A) On B) Under

(29) Average Daily Traffic

Is Above Half ADT?

(109) Precent Truck %

(30) Years of ADT

(19) Bypass, Detour Length Miles

APPRAISALS

(67) Structural Evaluation

(68) Deck Geometry

(69) Underclearances, Vert. & Horiz.

(71) Waterway Adequacy

(72) Approach Roadway Alignment

(113) Scour Critical

COMMENTS

- Items 29 & 30: Taken from CTDOT traffic monitoring website from 2020 adding 1% per year.

CLASSIFICATION

(112) NBIS Bridge Length

(104) Highway System

(26) Functional Class

(100) Defense Highway

(101) Parallel Structure

(102) Direction of Traffic

Form: BRI-19, Rev. 2/15
Inspection type: Routine
Inspection Date: 10/10/2023
Inspected by: TranSystems

:Bridge No 00848

Town: UNION
Carried: ROUTE 89
Crossed: INTERSTATE 84
Inventory Route: Non-NHS

(103) Temporary Structure
(110) Designated National Network
(20) Toll
(21) Maintain
(22) Owner
Report Class
(37) Historical Significance

POSTED SIGNS

Other Posted Sign 1
Other Posted Sign 2

	Actual	Recomended	
Posted Load Single Unit Truck	<input type="text"/>	<input type="text"/>	tons
Posted Load Semi-Trailer Truck	<input type="text"/>	<input type="text"/>	tons
Posted Load 4 Axle Truck	<input type="text"/>	<input type="text"/>	tons
Posted Load 3S2 Truck	<input type="text"/>	<input type="text"/>	tons
All Vehicles	<input type="text"/>	<input type="text"/>	tons

Posted Vert. Clearance on Bridge ft. in.

Posted Vert. Underclearance ft. in.

Posted Speed Limit on Bridge m.p.h.

OTHER FEATURES

Fence Required
Fence Present
Fence Type
Fence Height
Fence Material
Fence Top Type
Barrel Ladders
Stand Pipes
Catwalks
Moveable Inspection System
Haunches Present over Roadway

PROPOSED IMPROVEMENTS

(75A) Type of Work Proposed
(75B) Work Done By
(76) Length of Structure Improvement ft.
(94) Bridge Improvement Cost \$
(95) Roadway Improvement Cost \$
(96) Total Project Cost \$
(97) Year of Improvement Estimate
(114) Future ADT
(115) Year of Future ADT
DOT Bridge Program List No
Project No
Advertised Date

LOAD RATING & POSTING

(31) Design Load
(63) Operating Rating Type
(64) Operating Rating
(65) Inventory Rating Type
(66) Inventory Rating
Evaluation Code
Year of Evaluation
(70) Bridge Posting
(41) Structure Status

Form: BRI-19, Rev. 2/15

Inspection type: Routine

Inspection Date: 10/10/2023

Inspected by: TranSystems

:Bridge No 00848

Town: UNION

Carried: ROUTE 89

Crossed: INTERSTATE 84

Inventory Route: Non-NHS

Utilities	N No Utilities present
-----------	--------------------------

Form: BRI-19, Rev. 2/15
Inspection type: Routine
Inspection Date: 10/10/2023
Inspected by: TranSystems

:Bridge No 00848


Town: UNION
Carried: ROUTE 89
Crossed: INTERSTATE 84
Inventory Route: Non-NHS

INSPECTOR'S SIGNATURES:

1) _____ Date: 10/24/2023



2) _____ Date: 10/27/2023



3) _____ Date:

4) _____ Date:

P.E. SIGNATURE:



Date: 11/03/2023

P.E. #

0016495

Reviewed By:


Baihai Wang

Date: 12/19/2023

Form: BRI-25, Rev. 2/15
Inspection Type: Routine
Inspection Date: 10/10/2023
Inspected By: Vigliotti, Michael

Bridge No: 00848

Town: 77830 - UNION
Carried: ROUTE 89
Crossed: INTERSTATE 84
Inventory Route: 0

INVENTORY ROUTE UNDER STRUCTURE

IDENTIFICATION		AGE AND SERVICE	
Description:	Interstate 84	(28B) Number Of Inventory Route Lanes:	6
(5) Inventory Route:		(29) Average Daily Traffic:	51300
(A) Record Type:	2: Single route goes "under" the structure	(109) Percent Truck:	16
(B) Signing Prefix:	1 - INTERSTATE HIGHWAY	(30) Year Of ADT:	2018
(C) Level of Service:	1 - MAINLINE	(41) Inv Route Operational Status:	A - Open
(D) Route No.:	00084	(19) Bypass Detour Length:	0 Miles
(E) Directional Suffix:	0 - NOT APPLICABLE		
(11) Milepoint:	92.05		
GEOMETRIC DATA		CLASSIFICATION & POSTED SIGN	
(10) Inv. Rte. Min. Vert. Clearance:	16 ft. 1 in.	(26) Functional Class:	01 - Rural - Principal Arterial - Interstate
(47) Log Inv. Rte., Total Horiz. Clr.:	65.7 ft.	(100) Defense Highway:	1 - Is on an Interstate STRAHNET route
(Enter Largest Value of Log or Rlog from below)		(102) Direction of Traffic:	2 - 2-way traffic
Log Inv. Rte., Total Horiz. Clr.:	65.7 ft.	(104) Highway System:	1 - Structure/Route is on NHS
(Permit Purposes)		(110) Designated National Network:	1 - Inventory route on National Truck Network
RLog Inv. Rte., Total Horiz. Clr.:	65.3 ft.	Posted Vert. Clr. Under Bridge:	ft. in.
(Permit Purposes)			
Log Min. Vert. Clr. Over Bridge Roadway:	14 ft. 11 in.	COMMENTS	
(Travelway Only Under Bridge)		<div>Items 29 & 30: Taken from CTDOT 2018 Traffic Log</div>	
RLog Min. Vert. Clr. Over Bridge Roadway:	15 ft. 0 in.		
(Travelway Only Under Bridge)			
(55) Min. Lat. Underclearance on Right:	H ref. 15 ft. 0 in.		
(56) Min. Lat Underclearance on Left:	23 ft. 1 in.		

Form: BRI-18, Rev. 1/14
Inspection type: Routine
Inspection Date: 10/10/2023
Inspected by: TranSystems

:Bridge No 00848

Town: UNION
Carried: ROUTE 89
Crossed: INTERSTATE 84
Inventory Route: Non-NHS

FIELD INSPECTION REPORT

Location:	0.57 MI SOUTH OF RTE 190	Year Built:	1958	Snooper Required:	<input type="checkbox"/>
Main Material:	4 - Steel continuous	Year Rebuilt		Snooper Used:	<input type="checkbox"/>
Main Design:	02 - Stringer/Multi-beam or				

Inspectors:		Visits:			
Lead Inspector:	Michael Vigliotti	Visit Date:	Temp:	Start Time:	End Time:
Inspector:	Task:	10/10/2023	62	08:30 AM	01:30 PM
Andes,Carson	BSE - Inspector	10/13/2023	65	08:30 AM	12:30 PM
Schneider,Thomas	BSE - Inspector				
Vigliotti,Michael	BSE - Inspector				

58. DECK: Overall Rating: 5

Rating

- Overlay: 6

Bituminous concrete overlay:
 - Transverse and longitudinal cracks up to 10' long x 1/8" wide.
 - Paving seam up to 1/4" wide.
 - Core sample holes have been drilled and patched.
 - Southwest shoulder has a 4' wide x 3' long area of heaving.
 - Rating decreased from '8' to '6'.
See Top of deck General Notes sketch, Top of Deck sketch and photo 8.
- Deck - Str. Condition: 5

The underside of the concrete deck:
 - Random spalls up to 2'-6" long x 4'-6" wide x 4" deep, some spalls have adjacent 6" wide hollow areas and/or concrete inside the spall is hollow (over road) and the spalls are typically coated but exposed rebar has some re-rusting (Photos 10 & 11).
 - All deck haunches over the roadways have been previously removed (some hollow haunches over dirt).
 - Random hairline cracking with and without efflorescence.
 - Between the girder top flange and deck slab up to 1/2" gap at the locations with removed haunches.
 - Random 4"ø x 1/4" deep popouts with random shallow rebar.
The following (intact) hollow areas were found over the roadway:
 - Span 1, 2' long x 1' wide hollow area over right lane in bay 4, panel 2.
 - Span 2, 2' long x 10" wide dull/hollow area over left lane in bay 3, panel 3 (Photo 10).
 - Span 2, adjacent to the 5' long x 3' wide x 4-1/2" deep (coated) spall there are (2) hollow areas up to 6" away over the right lane/shoulder in bay 3, panel 4.
 - Span 2, 1' diameter hollow area over the slope protection/right shoulder in bay 3, panel 5.
 - Span 2, 1' long x 7" wide hollow area over center lane in bay 5, panel 3.
 - Approximate deck deterioration percentage: 12.5%.
See Underside of Deck & Framing - General Notes sketch, Underside of Deck & Framing sketches and photos 9-11 & 30.
- Curbs: 6

Concrete curbs are monolithic with the safety walks:
 - Random longitudinal and transverse hairline cracking and areas of moderate scale.
 - Interfaces with transition curbs have up to 1'-6" long x 4" high x 2" deep edge spalling.
 - Previous repairs are deteriorating.
 - Transition curbs are vertically misaligned/ lower up to 5".
 - Average curb reveal: West curb: 7"; East curb: 6".

Form: BRI-18, Rev. 1/14
Inspection type: Routine
Inspection Date: 10/10/2023
Inspected by: TranSystems

:Bridge No 00848

Town: UNION
Carried: ROUTE 89
Crossed: INTERSTATE 84
Inventory Route: Non-NHS

	- Northwest and southeast transition between concrete and approach curbs are missing up to 7" long. See Top of Deck General Notes sketch, Top of Deck sketch and photos 12-13.
Median: N	
Sidewalks: 6	See Item "Curbs" above.
Parapet: 5	Reinforced concrete parapets: - Random hairline cracking with and without efflorescence. - Isolated spalls up to 2' wide x 6" high x 2" deep (Photo 14). - Previous repairs have random cracks and minor spalling, with isolated intact hollow areas on top and outside faces (over roadways). - In spans 1 & 2, there are hollow areas on the outside face up to 6' long x 1' high over the dirt. The following (intact) hollow areas were found over the roadway: - Span 1, west fascia parapet with (2) hollow areas on the outside face up to 3' long x 1' high over the right lane/shoulder near abutment 1 (Photo 15). - Span 2, east fascia parapet with hollow area on the outside face 6" long x 1' high over the right shoulder near abutment 2. See Top of Deck General Notes sketch, Top of Deck sketch, Underside of Deck & Framing General Notes sketch, Underside of Deck & Framing sketches and photos 12-15.
Railing: 7	Throughout single pipe extruded aluminum rail: - Random railing posts have up to 4/4 anchor bolt nuts loose (Photo 16). See Top of deck General Notes sketch and photos 12, 13 and 16.
Paint: N	
Fence: N	
Drains: 6	- Between weeps and support steel, clips are typically rusted out throughout. See Underside of Deck & Framing General Notes sketch.
Lighting Standard: N	
Overall Utility Condition Rating	N - Not Applicable
Utility Type/Size	
N No Utilities present	
Construction Joints: N	
Expansion Joint: 7	- Adhesion cracks up to full length x 3/4" wide at both abutments (Photos 17 and 18). See Top of Deck General Notes sketch and Top of Deck sketch and photos 17 and 18.
Haunches Present over travelway?	NO

APPROACH CONDITION:

	Overall Rating: 6
--	-------------------

Rating

Approach Slab: N	None per available plans.
Relief Joints: N	
Approach Guide Rail: 6	Steel W-beam guide rail with weak posts: - Random areas up to 20' long with collisions damage and up to four (4) bent/disconnected posts (Photos 20 & 21). - The northwest guide rail has a 3/4" long tear.

Form: BRI-18, Rev. 1/14
 Inspection type: Routine
 Inspection Date: 10/10/2023
 Inspected by: TranSystems

:Bridge No 00848

Town: UNION
 Carried: ROUTE 89
 Crossed: INTERSTATE 84
 Inventory Route: Non-NHS

		- All transitions has up to 2" gap between parapet and approach guide rail (Photo 19).
		See Top of Deck General Notes sketch and Top of Deck sketch.
Approach Pavement:	6	Bituminous approach pavement: - The northeast approach pavement has a 12' long x 3/4" wide transverse crack. - The southeast approach pavement has a 20' long x 3/4" wide transverse crack. - Rating decreased from '7' to '6'.
		See Top of Deck General Notes sketch, Top of Deck sketch and photos 4-5.
Approach Embankment:	8	
<u>Traffic Safety Features</u>		
Bridge Railings:	0	Do not meet standards for Non-NHS structures (safety walk).
Transitions:	0	Do not meet R-B 350 standards (rub rails not attached to parapet).
Approach Guardrails:	0	Do not meet R-B 350 Standards (steel blockouts and weak posts).
Approach Guardrail Ends:	0	Do not meet R-B 350 Standards (transition to ground within clear zone).

59. SUPERSTRUCTURE:

Overall Rating: 4

Rating

Bearing Devices:	5	Expansion rocker bearings at both abutments: - Up to heavy laminated rust at components. - Up to 1/4" thick pack rust between the rockers and masonry plates. - Random anchor bolts are slightly tilted and/or have backed off nuts. - Bearings were in expansion or/neutral mode at 62° F (laminated rust affects some measurements). Fixed bearings at pier: - Light to moderate rust at plates; nuts and washers with laminated rust. - Pack rust up to 1/4" thick between the sole and masonry plates (worst at fascias). - Isolated sole plates overhang the masonry plates in span 2 up to 3/8" (<5% bearing contact area loss; as-built). - Random anchor bolts are short. - Isolated anchor bolt nuts are backed off up to 1/2". See Underside of Deck & Framing General Notes sketch, Underside of Deck & Framing sketches and photos 22-23.
Stringers:	N	
Girders:	4	Two (2) spans with seven (7) steel girders: - Areas of peeling paint with laminated rust - All girders in span 2 have laminated rust and section losses to bottom flanges in critical zones up to 3' long x full width x 3/16" deep resulting in 17% section loss, (worst location girders 2-4 in span 2) (Photos 24 & 25). - Girder webs near midspan have section loss up to 8" high x 1/8" deep (non-critical). - Random webs over bearings have up to 6" high x 1/8" deep losses (< 10% web loss in bearing) (Photo 26). - Intermediate diaphragms have up to 2" thick pack rust between lower members that is pushing/rotating the members apart causing the connection welds to crack/break. - Span 2, bay 1, second diaphragm lower member at midspan with rusted through hole (Photo 27). - Span 1, Girder 2 near midspan web plate at base is misaligned at splice 3/8" x 2"H. Rating decreased from '5' to '4' due to section loss on the bottom flange in critical area. See Item 'Collision Damage' below.

Form: BRI-18, Rev. 1/14
Inspection type: Routine
Inspection Date: 10/10/2023
Inspected by: TranSystems

:Bridge No 00848

Town: UNION
Carried: ROUTE 89
Crossed: INTERSTATE 84
Inventory Route: Non-NHS

		See Underside of Deck & Framing General Notes sketch, Underside of Deck & Framing sketches, Section Loss Details sketches, Girder 1 Collision Damage Detail (Plan View) and photos 9 & 28.
Floor Beams:	N	
Trusses - General:	N	
Trusses - Portals:	N	
Trusses - Bracing:	N	
Paint:	5	- Less than 50% of the painted surfaces are rusting
		See Item 'Girders' above.
		See Underside of Deck and Framing - General Notes sketch.
Rust:	5	See Items 'Bearing Devices' and 'Girders' above.
Machinery Movable Span:	N	
Rivets & Bolts:	N	
Welds - Cracks:	4	<ul style="list-style-type: none"> - Web and bottom flange splice welds are not ground smooth and have some minor undercutting (Photo 29). - Numerous welds at intermediate diaphragm connections are cracked/broken due to pack rust (Photo 27). - Random missing overhead welds at stiffener to diaphragm connections (other welds in place). - Span 1, several intermediate cross frames have the welds broken at each connection to the girder for one of the two lower horizontal back to back angles due to pack rust. This angle is now only supported by two (2) 2" x 3/8" x 3" steel plates welded to the top of the angles. Cross frame 3 in bay 2 have 3/16" long cracks at these steel connection plates. CTDOT was notified via phone call and 10/11/23 email. - Span 2, multiple intermediate cross frames have the welds broken at one connection to the girder for one of the two lower horizontal back to back angles due to pack rust. - Bottom base plates for OHSS 21635 are welded to girder 1 web in span 1 (Fatigue Category E). <p>Rating decreased from '5' to '4' due to broken welds on lower angles.</p> <p>See Underside of Deck & Framing General Notes sketch, Underside of Deck & Framing sketches and photos 27-29.</p>
Timber Decay:	N	
Concrete Cracking:	N	
Collision Damage:	5	<ul style="list-style-type: none"> - Random minor dents/gouges in bottom flanges up to 1/16" deep (ground smooth) - Girder 3, span 2, west bottom flange leg near midspan, bent upwards up to 1/4"; no change (construction). <p>Location of hit at Girder 1, 8th stiffener from Abutment 1 (14'-11" vertical clearance):</p> <ul style="list-style-type: none"> - Bottom Flange, West side, bent up 1-5/16" for 20" L w/ numerous gouges up to 1/4" deep (Photos 32-33). - Bottom Flange, East side, bent down 3/8" over 4' for 12" long. - Girder out of plane to the North up to 3-1/2" over approximately 22'. - Top flange separated from the deck for approximately 22' long x up to 13/16" high (no shear studs) (Photo 30). - Hole through web has been repaired with a bolted repair plate. <p>A laser aligned against the outside of the bottom flange above the bearing was used to determine how out of plane the girder is.</p> <p>Girder 2, West face:</p> <ul style="list-style-type: none"> - 9th stiffener from Abutment 1 bent out of plane up to 5/8" over 2'. Stiffener twisted from original position on bottom flange. - Web with 10" diameter area with 1/8" to 3/16" deep dent. Adjacent to this area there is a 3" diameter x up to 5/16" deep dent/gouge (Photo 34).

Form: BRI-18, Rev. 1/14
 Inspection type: Routine
 Inspection Date: 10/10/2023
 Inspected by: TranSystems

:Bridge No 00848

Town: UNION
 Carried: ROUTE 89
 Crossed: INTERSTATE 84
 Inventory Route: Non-NHS

	Decreased from '7' to '5'.
	See Underside of Deck & Framing General Notes sketch, Underside of Deck & Framing sketches, Girder 1 Collision Damage Detail (Plan View) and Photos 31 & 32.
Member Alignment: 5	- Random girder bottom flanges are wavy - Also, see Items "Bearing Devices" and "Collision Damage" above
	Rating decreased from '7' to '5'.
	See Underside of Deck & Framing General Notes sketch, Underside of Deck & Framing sketches and Photos 31-33.
Deflection Under Load: N	(N) Normal; (E) Excessive
Vibration Under Load: N	(N) Normal; (E) Excessive
Stand Pipes: N	
Catwalks: N	
Movable Inspection System: N	
Barrel Ladders: N	
Are Barrel Ladders OSHA Compliant? NA	

60. SUBSTRUCTURE:

Overall Rating: 6

Rating

Abutments - Stem: 7	Reinforced concrete abutment stems: - Random hairline cracking with isolated efflorescence (some cracks extend across seats). - Random concrete patches with isolated hairline cracks. - Pedestals have random hairline cracks. - Abutment 2 has a spall 7" wide x 5" high x 1/4" deep. - Both abutments have areas of light scale, light honeycombing, and isolated popouts. See Abutment sketch and photos 35-36.
Abutments - Backwall: 7	Reinforced concrete abutment backwalls: - Random vertical hairline cracking and areas of hairline mapcracking with isolated efflorescence. - Random chipping along top. - Construction joints are open up to 1/4" wide; (no change). See Abutment sketch and photos 35-36.
Abutments - Footings: N	Not visible.
Abutments - Settlement: 8	None noted.
Abutments - Wingwalls: 7	Reinforced concrete wingwalls - Isolated popouts/shallow rebar - The joint fill material is deteriorated/missing - Light to heavy vegetation growth along wingwalls - Wingwall 2B has a 4" diameter x 3/4" deep spall - Both abutments have areas of light scale, light honeycombing, and isolated popouts with random shallow rebar. See Abutment sketch and photos 37-38.
Piers/Bents - Caps: 6	Reinforced concrete pier cap: - Random hairline cracks with and without efflorescence. - Random spalls up to 4" long x 8" wide x 1-1/2" deep with exposed rebar. - Isolated hollow areas up to 16" x 18".

Form: BRI-18, Rev. 1/14
Inspection type: Routine
Inspection Date: 10/10/2023
Inspected by: TranSystems

:Bridge No 00848

Town: UNION
Carried: ROUTE 89
Crossed: INTERSTATE 84
Inventory Route: Non-NHS

		- Concrete patches along 75% of cap length, some with shrinkage/hairline cracking.
		See Pier sketch and photo 39.
Piers/Bents - Pile Bent:	N	
Piers/Bents - Columns:	7	Reinforced concrete pier columns: - Column 1, south elevation has a 6'-0" high x 2'-0" wide area of hairline mapcracks . See Pier sketch and photo 39.
Piers/Bents - Footings:	N	Not visible.
Piers/Bents - Settlement:	8	None noted.
Erosion - Scour:	7	Concrete block abutment slope protection has cracks in the mortar joints and blocks up to 1" wide Scour = 'N'. See Abutment sketch and photo 35.
Concrete Crack - Spall:	6	See Item 'Piers/Bents - Caps' above.
Steel Corrosion:	N	
Paint:	N	
Timber Decay:	N	
Collision Damage:	8	
Debris:	7	- Light sand debris on the abutment seats See Abutment sketch.

61. CHANNEL AND CHANNEL PROTECTION:

Overall Rating: N

Rating

Channel - Scour:	N	
Embankment - Erosion:	N	
Debris:	N	
Vegetation:	N	
Channel Change:	N	
Fender - System:	N	
Spur Dikes and Jetties:	N	
Rip Rap:	N	

62. CULVERTS AND RETAINING WALLS:

Overall Rating: N

Rating

Barrel:	N	
Concrete:	N	
Steel:	N	
Timber:	N	
Headwall:	N	
Cutoff Wall:	N	
Debris:	N	
Retaining Wall System:	N	

Footings: N	
-------------	--

LOAD POSTING:

Rating

Single Unit (Tons):		
Semi Trailer (Tons):		
4 Axle (Tons):		
3S2 (Tons):		
All Vehicles:		
Advanced Warning:		
Warning At Bridge:		
Legibility:		
Visibility:		

VERTICAL CLEARANCE POSTING

Min. Vert Under Clearance:	14	Ft	11	In	See Clearance Diagram.
Posted Clearance Under Bridge:		Ft		In	
Posted Clearance On Bridge:		Ft		In	
Advanced Warning:					
Warning At Bridge:					
Legibility:					
Visibility:					

NOTES / COMMENTS:

Character of Traffic: Light to moderate volume and mixed weights.

Additional Notes:

Bridge ID is clear and legible (Photo 1).
Bridge is labeled from south to north and girders are numbered from west to east, which is consistent with the previous inspection report, log direction of Route 89, and the bridge plans.
Bridge was inspected using a 30' lift truck with vendor provider single and double lane closures on I-84 and a state trooper.

Additional Comments:

There are three In-Depth components associated with this bridge.
There are three (3) new and five (5) outstanding Highway Maintenance Work Items associated with this bridge (00848-2019-0010, 00848-2019-0009, 00848-2019-0008, 00848-2019-0007, and 00848-2019-0006).
Work item 00848-2019-0010 has been updated to current conditions.

National Bridge Elements**Inspection type:** Routine**Inspection Date:** 10/10/2023**Inspected by:** TranSystems**:Bridge No 00848****Town:** UNION**Carried:** ROUTE 89**Crossed:** INTERSTATE 84**Inventory Route:** Non-NHS

	Environment	Total Quantity	Units	Condition State 1	Condition State 2	Condition State 3	Condition State 4
12 - Reinforced Concrete Deck	Mod.	8620	sq. ft.	7542	997	81	0
1080 - Delamination/Spall/Patched Area		99		0	21	78	0
1090 - Exposed Rebar		17		0	14	3	0
1120 - Efflorescence/Rust Staining		842		0	842	0	0
1130 - Cracking (RC and Other)		120		0	120	0	0
510 - Wearing Surfaces		7486	sq. ft.	7462	24	0	0
3230 - Effectiveness (Wearing Surface)		24		0	24	0	0
107 - Steel Open Girder/Beam	Mod.	1351	ft.	794	411	117	29
1000 - Corrosion		517		0	405	83	29
7000 - Damage		40		0	6	34	0
515 - Steel Protective Coating		21886	sq. ft.	17506	0	0	4380
3440 - Effectiveness (Steel Protective Coatings)		4380		0	0	0	4380
205 - Reinforced Concrete Column	Mod.	3	each	2	1	0	0
1130 - Cracking (RC and Other)		1		0	1	0	0
215 - Reinforced Concrete Abutment	Mod.	128	ft.	96	32	0	0
1080 - Delamination/Spall/Patched Area		17		0	17	0	0
1120 - Efflorescence/Rust Staining		2		0	2	0	0
1130 - Cracking (RC and Other)		13		0	13	0	0
234 - Reinforced Concrete Pier Cap	Mod.	46	ft.	4	40	2	0
1080 - Delamination/Spall/Patched Area		37		0	35	2	0
1120 - Efflorescence/Rust Staining		3		0	3	0	0
1130 - Cracking (RC and Other)		2		0	2	0	0
306 - Other Joint	Mod.	82	ft.	9	73	0	0
2310 - Leakage		73		0	73	0	0
311 - Movable Bearing	Mod.	14	each	0	5	9	0
1000 - Corrosion		12		0	5	7	0
1020 - Connection		2		0	0	2	0
515 - Steel Protective Coating		14	sq. ft.	2	0	0	12
3440 - Effectiveness (Steel Protective Coatings)		12		0	0	0	12
313 - Fixed Bearing	Mod.	7	each	0	4	3	0
1000 - Corrosion		4		0	1	3	0
1020 - Connection		3		0	3	0	0
515 - Steel Protective Coating		7	sq. ft.	3	0	0	4
3440 - Effectiveness (Steel Protective Coatings)		4		0	0	0	4
330 - Metal Bridge Railing	Mod.	394	ft.	393	1	0	0
1020 - Connection		1		0	1	0	0
331 - Reinforced Concrete Bridge Railing	Mod.	394	ft.	177	215	2	0
1080 - Delamination/Spall/Patched Area		117		0	115	2	0
1120 - Efflorescence/Rust Staining		40		0	40	0	0
1130 - Cracking (RC and Other)		60		0	60	0	0

FIELD NOTES

BRIDGE NO.: 00848
CREW: KG,NC (ADA)

DATE: 11/15/2021
SHEET: 1

ROCKER BEARING MEASUREMENTS

Form BRI-15, Rev. 9/97

Span No. : 1


Substructure
Unit = Abutment 1

Temp. = 47 °F

$$\theta = \sin^{-1} (F-B)/W$$

$$Y = R \tan \theta$$

The "Front" of the bearing is the side facing the fixed bearing.



W = 8 in

NOTE:

"F" & "B" should be measured at the left side corners of the rocker or on the side closest to the front face of the substructure on skewed bridges.

Beam	"F"	"B"	Y	Cont. Or Exp.	Comments
G1	1 1/8	1 1/16	1/16	E	Heavy to LR on masonry PL & east AB nut
G4	1 1/2	1 1/2	0	N	W. side PL attached to sole PL w/ FH crack in vt front weld due to
G7	1 3/4	1 1/8	10/16	E	Mod to heavy rust; E. Ab nut backed off 1 1/2" H; LR on masonry PL up to 3/8" thick
MEV, TAS (TSC) 10/10/23 62°F					
G1	1 1/8	1	2/16	E	Heavy to LR on masonry PL & east AB nut
G4	1 1/2	1 1/2	0	N	W. side PL attached to sole PL w/ FH crack in vt front weld due to IR. W. side missing keeper block at sole plate
G7	1 7/16	1 1/16	6/16	E	Mod to heavy rust; E. Ab nut backed off 1 1/2" H; LR on masonry PL up to 3/8" thick
GENERAL NOTES:					
- Random ABs are slightly tilted, Random AB washers bent due to pack rust					
- Mod rust typical					
- Pack rust up to 1/4" thick between rocker and masonry PL's					
- All bearings show visible evidence of movement					

FRACTURE CRITICAL MEMBERS / FRACTURE PRONE DETAILS

Inspectors:		Visits:			
Lead Inspector:	Michael Vigliotti	Visit Date:	Temp:	Start Time:	End Time:
Inspector:	Task:	10/10/2023	62	08:30 AM	01:30 PM
Andes,Carson	BSE - Inspector	10/13/2023	65	08:30 AM	12:30 PM
Schneider,Thomas	BSE - Inspector				
Vigliotti,Michael	BSE - Inspector				

Fracture Critical Inspection Frequency: Months

Fracture Critical Type Code:

Structure Type: Highway Bridges Year Built: 1958 ADT: 930 Year of ADT: 2023 % Truck: 6

Access Equipment Needed: 40' Lift Truck

Traffic Control Required: Single right lane closure on I-84 EB.

Reference to Plans: Project No. 145-58

MEMBER/DETAIL TYPE # 1

Member/Details Type: H Highly fatigue prone details in tension areas

Fracture Critical: No

Fatigue Category: E

Steel Type: A-36

Fatigue Prone: Yes

Description: Bottom base plates for OHSS 21635 are welded to the web of girder 1 in span 1 in tension zone (>4"L longitudinal weld).

Inspection Procedure: Hands-on

Condition Comments: No significant deficiencies.

Procedure Followed This Inspection? Yes If No please explain:


Sketches

Inspection type: Routine
 Inspection Date: 10/10/2023
 Inspected by: TranSystems

:Bridge No 00848

Town: UNION
 Carried: ROUTE 89
 Crossed: INTERSTATE 84
 Inventory Route: Non-NHS

CREW: KT, MRJ	DATE: 10/17/2017	BRIDGE NO.: 00848
---------------	------------------	-------------------



Clearance Diagram
 N.T.S.

REVISION	DATE: 10/3/2019	CREW: BF, TK (Baker)	REVISION	DATE: 10/13/23	CREW: MEV, TAS, CJA (TSC)
REVISION	DATE: 10/18/2021	CREW: KG, NC (ADA)	REVISION	DATE:	CREW:

Sketches

Inspection type: Routine

Inspection Date: 10/10/2023

Inspected by: TranSystems

:Bridge No 00848

Town: UNION

Carried: ROUTE 89

Crossed: INTERSTATE 84

Inventory Route: Non-NHS

Sketches

Inspection type: Routine
Inspection Date: 10/10/2023
Inspected by: TranSystems

:Bridge No 00848

Town: UNION
Carried: ROUTE 89
Crossed: INTERSTATE 84
Inventory Route: Non-NHS

CREW: MRJ, KT	DATE: 10/17/2017	BRIDGE NO.: 00848
---------------	------------------	-------------------

Overlay:

- Transverse and longitudinal cracks up to 10'L x 1/8"W
- Paving seam up to 1/4"W
- Core sample holes have been drilled and patched

Curbs/Safety Walk:

- Concrete curbs are monolithic with safety walks
- Curbs/safety walk has random transverse and longitudinal hairline cracks and areas of moderate scale
- Past concrete repairs have cracks and are beginning to chip/spall
- Average curb reveal: West curb: 7"; East Curb: 6"
- Granite approach curbs have chipped edges and rust stains at random locations
- Transition curbs vertically misaligned up to 5" with bridge curbs

Parapet:

- Concrete parapets and end blocks have areas of scale up to 1/2"D, random vertical hairline cracks and areas of map cracking, both with random efflo
- Past concrete repairs have cracks and are beginning to chip/spall (worst along top of west parapet, above pier)

Railing (aluminum):

- Random railing posts have up to 4/4 anchor bolt nuts loose

Joints:

- Asphaltic plug joints at both abutments

Approach Guide Rail:

- Approach guide rails has minor impact damage, dents and scrapes
- All transitions has up to 2" gap between parapet and approach guardrail





Approach Pavement:

- Approach pavements have been repaved since the previous inspection
- Approaches have longitudinal and transverse cracks up to 20'L x 3/4"W

Jersey Barrier:

- Scattered spalls up to 2'L x 10'H x 2"D with exposed rebar

Top of Deck General Notes

REVISION 	DATE: 10/3/2019	CREW: BF, TK (Baker)	REVISION 	DATE: 10/10/23	CREW: MEV, TAS (TSC)
REVISION 	DATE: 10/18/2021	CREW: KG, NC (ADA)	REVISION 	DATE:	CREW:

Sketches

Inspection type: Routine
 Inspection Date: 10/10/2023
 Inspected by: TranSystems

:Bridge No 00848

Town: UNION
 Carried: ROUTE 89
 Crossed: INTERSTATE 84
 Inventory Route: Non-NHS

CREW: MRJ, KT	DATE: 10/17/2017	BRIDGE NO.: 00848
---------------	------------------	-------------------

Detail Notes:

① NW curb missing 7"L between concrete and approach curb

② 4" vertical misalignment between concrete and dirt embankment

Log Direction of
South to North

The sketch shows a plan view of the bridge deck with the following features and annotations:

- Abutment 1 (APJ):** Located on the left side. Annotations include:
 - 4"W x 3"L area of heaving
 - Adhesion crack FL x 3/4"W
 - 20'L x 3/4"W
 - (4) bent/disconnected posts ±40' from bridge
- Pier:** Located between the spans. Annotation: 10"L x 4"W x 1/2"DP (on top of parapet)
- Abutment 2 (APJ):** Located on the right side. Annotations include:
 - 1.5'L x 4"H x 2"DP (corner of curb)
 - (3) bent/disconnected posts ±40' from bridge w/ (1) twisted post w/ 3/4"L tear and w/ +/- 75' from bridge collision damage
 - Adhesion crack 20'L x up to 1/4"W SWL
 - 12'L x 3/4"W TV crk
 - 13'L x 1/2"W adhesion crack
 - (2) areas of collision damage up to 20'L w/ rand bent posts ±50' & ±75' from bridge w/ (1) discon. post
- Span 1:** Between Abutment 1 and Pier. Annotations include:
 - 12"x8"x2"DP
 - 5"L missing curb between conc. and appr. curb
 - 5" vertical misalignment between conc. and dirt embankment
- Span 2:** Between Pier and Abutment 2.
- Other Features:**
 - Safety walk
 - Shoulder
 - DYL (Dotted white line)
 - SWL (Solid white line)
 - Route 89 (indicated by an arrow pointing left)

Legend + Full Legend:

Ⓐ - Adhesion cracking

☐ - Catch basin

DYL - Dotted white line

SWL - Solid white line

General Notes:

-See top of deck general notes sheet

Top of Deck
N.T.S.

REVISION	DATE: 10/3/2019	CREW: BF, TK (Baker)	REVISION	DATE: 10/10/23	CREW: MEV, TAS (TSC)
REVISION	DATE: 10/18/2021	CREW: KG, NC (ADA)	REVISION	DATE:	CREW:

Sketches**Inspection type:** Routine**Inspection Date:** 10/10/2023**Inspected by:** TranSystems**:Bridge No 00848****Town:** UNION**Carried:** ROUTE 89**Crossed:** INTERSTATE 84**Inventory Route:** Non-NHS

CREW: MRJ, KT	DATE: 10/17/2017	BRIDGE NO.: 00848
----------------------	-------------------------	--------------------------

Underside of Deck

- All haunches over roadway have been removed and some haunches over dirt were removed/spalled
- Between the girder top flange and deck slab there is up to 1/2" gap/PR at the locations with previously removed haunches
- Random hollow haunches over dirt
- Random 4"ø x 1/4" deep popouts with and without rebar
- Deck underside at fascias with hairline cracks with random efflorescence
- Approximately 12.5% total deck deterioration.

Drains

- Steel support clips attached to the bottom of the weep pipes have areas of moderate to heavy rust; rusted out at weeps
- Weeps extend below bottom flanges U.O.N.

Fixed Bearings

- Bearings at the pier has light to moderate rust and impacted rust up to 1/4" thick between sole and masonry plates
- Isolated sole plates overhang the masonry plates in span 2 by up to 3/8"; as-built
- Random anchor bolts are short up to 2 threads and anchor bolt nuts are backed off up to 1/2" at isolated locations
- AB nuts and washers w/ heavy LR

Girders

- Girders have areas of peeling paint with up to heavy laminated rust at random locations (negligible section loss U.O.N.)
- Areas of painted over section loss FW x up to 1/16" deep in the girder bottom flanges and lower webs at random locations (<5% bottom flange loss)
- At random web stiffeners, the adjacent bottom flanges have up to 5"W x 1/8" deep section loss
- Webs at these locations have up to 3" high x 1/8" deep loses (away from bearings)
- Bottom flange section losses are <5% in critical zones; U.O.N.
- Girder bottom flanges are wavy (worst in span 1 at G6); as-built
- Dents/gouges in girder bottom flanges up to 1/16" deep (ground smooth)
- At removed/spalled deck haunches, the exposed edges of the girder top flanges show heavy rust with less than 1/16" section loss
- Cross-frames has random areas of light to moderate rust and areas of laminated rust with up to 1/8" deep section loss at some locations
- Less than 50% paint surface rusting

Debris

- Light accumulation of concrete debris, pigeon waste and bird nests on top of girder bottom flanges at random locations

Welds/Cracks

- Cross frame welds are typically sloppy throughout
- Random missing horizontal overhead welds at stiffener to diaphragm angle connections (connections secure)
- Random cross frame bottom angles are rotated due to pack rust at locations with broken/missing horizontal welds
- Web and bottom flange splice welds are not ground smooth

Underside of Deck & Framing - General Notes


REVISION	DATE: 10/3/2019	CREW: TK, BF (Baker)	REVISION	DATE: 10/13/23	CREW: MEV, TAS, CJA (TSC)
REVISION	DATE: 10/18/2021	CREW: KG, NC (ADA)	REVISION	DATE:	CREW:

Sketches

Inspection type: Routine
Inspection Date: 10/10/2023
Inspected by: TranSystems

:Bridge No 00848

Town: UNION
Carried: ROUTE 89
Crossed: INTERSTATE 84
Inventory Route: Non-NHS



Sketches

Inspection type: Routine
Inspection Date: 10/10/2023
Inspected by: TranSystems





:Bridge No 00848

Town: UNION
Carried: ROUTE 89
Crossed: INTERSTATE 84
Inventory Route: Non-NHS

CREW: MRJ, BF	DATE: 10/3/2019	BRIDGE NO.: 00848
---------------	-----------------	-------------------

Bottom FL SL Calculation:
 $SL = (8.8'')(1/8'') = 1.1 \text{ in}^2$
 $Orig = (18'')(1'') = 18 \text{ in}^2$
 $(1.1 / 18)(100) = 6.11\%$

flange width = 18"
flange thickness = 1"
web thickness = 0.375"



Note:
All losses have laminated rust

Section Loss Details - Span 1
N.T.S.

REVISION	DATE: 10/18/2021	CREW: KG, NC (ADA)	REVISION	DATE:	CREW:
REVISION	DATE: 10/10/23	CREW: MEV, TAS (TSC)	REVISION	DATE:	CREW:


Sketches

Inspection type: Routine
Inspection Date: 10/10/2023
Inspected by: TranSystems

:Bridge No 00848

Town: UNION
Carried: ROUTE 89
Crossed: INTERSTATE 84
Inventory Route: Non-NHS

CREW: Team 17	DATE: 10/20/2022	BRIDGE NO.: 00848
---------------	------------------	-------------------



Girder 1 Collision Damage Detail (Plan View)

NTS


REVISION	DATE: 10/10/23	CREW: MEV, TAS, CJA (TSC)	REVISION	DATE:	CREW:
REVISION	DATE:	CREW:	REVISION	DATE:	CREW:

Sketches

Inspection type: Routine
Inspection Date: 10/10/2023
Inspected by: TranSystems

:Bridge No 00848

Town: UNION
Carried: ROUTE 89
Crossed: INTERSTATE 84
Inventory Route: Non-NHS



Sketches


Inspection type: Routine
Inspection Date: 10/10/2023
Inspected by: TranSystems

:Bridge No 00848

Town: UNION
Carried: ROUTE 89
Crossed: INTERSTATE 84
Inventory Route: Non-NHS


CREW: MRJ, KT	DATE: 10/17/2017	BRIDGE NO.: 00848
---------------	------------------	-------------------

Bottom FL SL Calculation:
 $SL = (8.8'')(3/16'') = 1.65 \text{ in}^2$
 $Orig = (18'')(7/8'') = 15.75 \text{ in}^2$
 $(1.65 / 15.75)(100) = 10\%$




Span 2, girder 1, Looking North
(Section A-A)

Bottom FL SL Calculation:
 $SL = (8.8'')(3/16'') + (8.8'')(1/8'') = 2.75 \text{ in}^2$
 $Orig = (18'')(7/8'') = 15.75 \text{ in}^2$
 $(2.75 / 15.75)(100) = 17\%$




Span 2, girders 2-4, Looking North
(Section B-B)

Bottom FL SL Calculation:
 $SL = (8.8'')(1/8'') + (8.8'')(1/8'') = 2.2 \text{ in}^2$
 $Orig = (18'')(7/8'') = 15.75 \text{ in}^2$
 $(2.2 / 15.75)(100) = 13.9\%$



Span 2, girders 5, Looking North
(Section C-C)

Bottom FL SL Calculation:
 $SL = (8.8'')(1/8'') + (8.8'')(1/16'') = 1.65 \text{ in}^2$
 $Orig = (18'')(7/8'') = 15.75 \text{ in}^2$
 $(1.65 / 15.75)(100) = 10\%$



Span 2, girder 6, Looking North
(Section D-D)

Note:
All losses have laminated rust

Section Loss Details - Span 2 Looking North
N.T.S.

REVISION	DATE: 10/3/2019	CREW: TK, BF (Baker)	REVISION	DATE: 10/10/23	CREW: MEV, TAS, CJA (TSC)
REVISION	DATE: 10/18/2021	CREW: KG, NC (ADA)	REVISION	DATE:	CREW:

Sketches


Inspection type: Routine
Inspection Date: 10/10/2023
Inspected by: TranSystems

:Bridge No 00848

Town: UNION
Carried: ROUTE 89
Crossed: INTERSTATE 84
Inventory Route: Non-NHS

CREW: MRJ, KT	DATE: 10/17/2017	BRIDGE NO.: 00848
---------------	------------------	-------------------


Bottom FL SL Calculation:
 $SL = (5'')(1/8'') = 0.625 \text{ in}^2$
 $Orig = (18'')(7/8'') = 15.75 \text{ in}^2$
 $(0.625 / 15.75) (100) = 4\%$



2'L x 5"W x 3/4" rem

Span 2, girder 7, Looking North
(Section E-E)


Bottom FL SL Calculation:
 $SL = (8.8'')(3/16'') = 1.65 \text{ in}^2$
 $Orig = (18'')(7/8'') = 15.75 \text{ in}^2$
 $(1.65 / 15.75) (100) = 10\%$



7'L x FW x 11/16" rem

Span 2, girder 2, Looking North
(Section F-F)


Bottom FL SL Calculation:
 $SL = (7.5'') * (1/8'') = 0.938 \text{ in}^2$
 $Orig = (18'')(7/8'') = 15.75 \text{ in}^2$
 $0.938 / 15.75 * (100) = 6\%$



8'L x FW x 3/4" rem

Span 2, girder 3, Looking North
(Section G-G)
(three closely spaced locations
within 8'L area)

Bottom FL SL Calculation:
 $SL = (8.8'')(1/8'') = 1.1 \text{ in}^2$
 $Orig = (18'')(7/8'') = 15.75 \text{ in}^2$
 $(1.1 / 15.75) (100) = 7\%$







2'L x FW x 3/4" rem

Span 2, girder 6, Looking North
(Section H-H)

Note:
All losses have laminated rust

Section Loss Details - Span 2 Looking North
N.T.S.

REVISION 	DATE: 10/3/2019	CREW: TK, BF (Baker)	REVISION 	DATE: 10/10/23	CREW: MEV, TAS, CJA (TSC)
REVISION 	DATE: 10/18/2021	CREW: KG, NC (ADA)	REVISION 	DATE:	CREW:



Sketches

Inspection type: Routine
 Inspection Date: 10/10/2023
 Inspected by: TranSystems

:Bridge No 00848

Town: UNION
 Carried: ROUTE 89
 Crossed: INTERSTATE 84
 Inventory Route: Non-NHS

CREW: KT, MRJ	DATE: 10/17/2017	BRIDGE NO.: 00848
---------------	------------------	-------------------



General Notes (Abutment):

- Random hairline cracks in pedestals
- Random cracks in stem and backwall extend across seat
- Random concrete patches (+/-10%)
- Areas of light scale, light honeycombing and isolated popouts
- Random spotty chipping along top of backwall
- Past water leakage stains on backwall
- Light sand debris on abutment seat
- Random cracks in concrete slope protection along mortar joints and in blocks, up to 1" wide

General Notes (Wingwalls):

- Areas of light scale, light honeycombing and isolated popouts with random shallow rebar
- Joint fill material deteriorated/missing
- Light to heavy vegetation growth along wingwalls
- Hairline cracks in the concrete retaining walls

LEGEND:

- HOLLOW AREA
- SHALLOW REBAR
- SPALL AREA
- SPALL AREA WITH EXPOSED REBAR
- MAPCRACKS
- HAIRLINE CRACKS
- HONEYCOMB AREA
- SCALE AREA
- EFFLORESCENCE PRESENT

REVISION	DATE: 10/3/2019	CREW: BF, TK (Baker)	REVISION	DATE: 10/10/23	CREW: MEV, TAS (TSC)
REVISION	DATE: 10/18/2021	CREW: KG, NC (ADA)	REVISION	DATE:	CREW:

Inspection type: Routine
Inspection Date: 10/10/2023
Inspected by: TranSystems

Town: UNION
Carried: ROUTE 89
Crossed: INTERSTATE 84
Inventory Route: Non-NHS

33

Form: Asset Photos
Inspection type: Routine
Inspection Date: 10/10/2023
Inspected by: TranSystems

:Bridge No 00848

Town: UNION
Carried: ROUTE 89
Crossed: INTERSTATE 84
Inventory Route: Non-NHS



Photo Number: 1

Bridge ID.

Photo Taken: 10/10/2023



Photo Number: 2

West elevation of the bridge.

Photo Taken: 10/13/2023

Form: Asset Photos
Inspection type: Routine
Inspection Date: 10/10/2023
Inspected by: TranSystems

:Bridge No 00848

Town: UNION
Carried: ROUTE 89
Crossed: INTERSTATE 84
Inventory Route: Non-NHS



Photo Number: 3

Photo Taken: 10/13/2023

East elevation of the bridge.



Photo Number: 4

Photo Taken: 10/10/2023

Bridge from south approach.

Form: Asset Photos
Inspection type: Routine
Inspection Date: 10/10/2023
Inspected by: TranSystems

:Bridge No 00848

Town: UNION
Carried: ROUTE 89
Crossed: INTERSTATE 84
Inventory Route: Non-NHS



Photo Number: 5

Photo Taken: 10/10/2023

Bridge from north approach.



Photo Number: 6

Photo Taken: 10/10/2023

South approach from bridge.

Form: Asset Photos
Inspection type: Routine
Inspection Date: 10/10/2023
Inspected by: TranSystems

:Bridge No 00848

Town: UNION
Carried: ROUTE 89
Crossed: INTERSTATE 84
Inventory Route: Non-NHS



Photo Number: 7

Photo Taken: 10/10/2023

North approach from bridge.



Photo Number: 8

Photo Taken: 10/10/2023

Typical top of deck. Note transverse and longitudinal cracks up to 10' long x 1/8" wide.

Form: Asset Photos
Inspection type: Routine
Inspection Date: 10/10/2023
Inspected by: TranSystems

:Bridge No 00848

Town: UNION
Carried: ROUTE 89
Crossed: INTERSTATE 84
Inventory Route: Non-NHS



Photo Number: 9

Typical underside of deck and framing, span 1.

Photo Taken: 10/10/2023



Photo Number: 10

Span 2, bay 3, panel 3. Note spalls with exposed rebar and adjacent hollow areas.

Photo Taken: 10/13/2023

Form: Asset Photos
Inspection type: Routine
Inspection Date: 10/10/2023
Inspected by: TranSystems

:Bridge No 00848

Town: UNION
Carried: ROUTE 89
Crossed: INTERSTATE 84
Inventory Route: Non-NHS



Photo Number: 11

Photo Taken: 10/10/2023

Span 2, bay 3, panel 2. Note spall with debonded rebar.



Photo Number: 12

Photo Taken: 10/17/2023

West parapet, bridge railing, safety walk, and jersey barrier.

Form: Asset Photos
Inspection type: Routine
Inspection Date: 10/10/2023
Inspected by: TranSystems

:Bridge No 00848

Town: UNION
Carried: ROUTE 89
Crossed: INTERSTATE 84
Inventory Route: Non-NHS



Photo Number: 13

Photo Taken: 10/17/2023

East parapet, bridge railing, and safety walk.



Photo Number: 14

Photo Taken: 10/17/2023

West parapet over the pier. Note the spall around the post.

Form: Asset Photos
Inspection type: Routine
Inspection Date: 10/10/2023
Inspected by: TranSystems

:Bridge No 00848

Town: UNION
Carried: ROUTE 89
Crossed: INTERSTATE 84
Inventory Route: Non-NHS



Photo Number: 15

Photo Taken: 10/10/2023

Span 1, west parapet near abutment 1 with hollow area.



Photo Number: 16

Photo Taken: 10/10/2023

East parapet railing post 13 with loose anchor bolt nuts.

Form: Asset Photos
Inspection type: Routine
Inspection Date: 10/10/2023
Inspected by: TranSystems

:Bridge No 00848

Town: UNION
Carried: ROUTE 89
Crossed: INTERSTATE 84
Inventory Route: Non-NHS



Photo Number: 17

Photo Taken: 10/10/2023

Asphaltic plug joint at abutment 1, looking east. Note the adhesion crack.



Photo Number: 18

Photo Taken: 10/10/2023

Asphaltic plug joint at abutment 2, looking west. Note the adhesion crack.

Form: Asset Photos
Inspection type: Routine
Inspection Date: 10/10/2023
Inspected by: TranSystems

:Bridge No 00848

Town: UNION
Carried: ROUTE 89
Crossed: INTERSTATE 84
Inventory Route: Non-NHS



Photo Number: 19

Photo Taken: 10/10/2023

Northeast transition with a gap, typical.



Photo Number: 20

Photo Taken: 10/10/2023

Northeast approach guide rail, looking north. Note the collision damage.

Form: Asset Photos
Inspection type: Routine
Inspection Date: 10/10/2023
Inspected by: TranSystems

:Bridge No 00848

Town: UNION
Carried: ROUTE 89
Crossed: INTERSTATE 84
Inventory Route: Non-NHS



Photo Number: 21

Photo Taken: 10/10/2023

Northwest approach guide rail, looking north. Note the collision damage and disconnected posts



Photo Number: 22

Photo Taken: 10/10/2023

Span 1, girder 7 at abutment 1. Note rocker bearing with laminated rust.

Form: Asset Photos

Inspection type: Routine

Inspection Date: 10/10/2023

Inspected by: TranSystems

:Bridge No 00848

Town: UNION

Carried: ROUTE 89

Crossed: INTERSTATE 84

Inventory Route: Non-NHS



Photo Number: 23

Photo Taken: 10/10/2023

Span 1, girder 4 at abutment 1. Note rocker bearing with laminated rust and missing keeper block on the west elevation.



Photo Number: 24

Photo Taken: 10/13/2023

Span 2, girder 4, west elevation near midspan. Note laminated rust and section loss at bottom flange.

Form: Asset Photos
Inspection type: Routine
Inspection Date: 10/10/2023
Inspected by: TranSystems

:Bridge No 00848

Town: UNION
Carried: ROUTE 89
Crossed: INTERSTATE 84
Inventory Route: Non-NHS



Photo Number: 25

Photo Taken: 10/13/2023

Span 2, girder 2, east elevation near panel 4. Note laminated rust and section loss at bottom flange.



Photo Number: 26

Photo Taken: 10/13/2023

Span 1, girder 1 west elevation near pier. Laminated rust and section loss in the web and bottom flange.

Form: Asset Photos
Inspection type: Routine
Inspection Date: 10/10/2023
Inspected by: TranSystems

:Bridge No 00848

Town: UNION
Carried: ROUTE 89
Crossed: INTERSTATE 84
Inventory Route: Non-NHS



Photo Number: 27
Span 1, bay 2, first intermediate diaphragm. Note deformed/bent lower members and broken overhead welds due to pack rust. Photo Taken: 10/17/2023



Photo Number: 28
Span 2, bay 1, second diaphragm with a rusted through hole in the lower angle. Photo Taken: 10/17/2023

Form: Asset Photos
Inspection type: Routine
Inspection Date: 10/10/2023
Inspected by: TranSystems

:Bridge No 00848

Town: UNION
Carried: ROUTE 89
Crossed: INTERSTATE 84
Inventory Route: Non-NHS



Photo Number: 29

Photo Taken: 10/17/2023

Span 1, girder 1, looking west. Note the web and bottom flange splice welds not ground smooth, typical.



Photo Number: 30

Photo Taken: 10/17/2023

Span 1, girder 1, west elevation above collision damage. Note the gap between girder top flange and deck.



Photo Number: 31

Photo Taken: 10/17/2023

Span 1, girder 1 west elevation web with repair plate at the collision damage.



Photo Number: 32

Photo Taken: 10/17/2023

Span 1, girder 1 bottom flange west elevation bent up and to the east.

Form: Asset Photos
Inspection type: Routine
Inspection Date: 10/10/2023
Inspected by: TranSystems

:Bridge No 00848

Town: UNION
Carried: ROUTE 89
Crossed: INTERSTATE 84
Inventory Route: Non-NHS



Photo Number: 33

Photo Taken: 10/17/2023

Span 1, girder 1 underside of bottom flange at the collision damage.



Photo Number: 34

Photo Taken: 10/10/2023

Span 1, girder 2, west elevation over right lane. Note the bent stiffener and dent with adjacent gouge in the web.

Form: Asset Photos
Inspection type: Routine
Inspection Date: 10/10/2023
Inspected by: TranSystems

:Bridge No 00848

Town: UNION
Carried: ROUTE 89
Crossed: INTERSTATE 84
Inventory Route: Non-NHS



Photo Number: 35

Photo Taken: 10/17/2023

Abutment 1.



Photo Number: 36

Photo Taken: 10/17/2023

Abutment 2.

Form: Asset Photos
Inspection type: Routine
Inspection Date: 10/10/2023
Inspected by: TranSystems

:Bridge No 00848

Town: UNION
Carried: ROUTE 89
Crossed: INTERSTATE 84
Inventory Route: Non-NHS



Photo Number: 37

Photo Taken: 10/17/2023

Wingwall 2B.



Photo Number: 38

Photo Taken: 10/17/2023

Wingwall 1B

Form: Asset Photos
Inspection type: Routine
Inspection Date: 10/10/2023
Inspected by: TranSystems

:Bridge No 00848

Town: UNION
Carried: ROUTE 89
Crossed: INTERSTATE 84
Inventory Route: Non-NHS



Photo Number: 39

Pier, looking south.

Photo Taken: 10/17/2023

Form: Maintenance
Carried: ROUTE 89
Crossed: INTERSTATE 84

:Bridge No 00848

Town: UNION
Inventory Route: Non-NHS

Status:	Bridge Maintenance Garage	Assigned To:	District_1 Bridge	Work Item ID:	00848-2023-0017
Date Issued:	11/09/2023	Priority:	Routine Repair		
Deficiency:	Deck Joint				
Structural Component:	Deck				
Comments:	Adhesion cracks up to full length x 3/4" wide at both abutments.				

Date Completed:	Actual Quantity:
-----------------	------------------



Asphaltic plug joint at abutment 1, looking east. Note the adhesion crack.

Form: Maintenance
Carried: ROUTE 89
Crossed: INTERSTATE 84

:Bridge No 00848

Town: UNION
Inventory Route: Non-NHS

Status: Bridge Maintenance Garage
Assigned To: District_1 Bridge
Work Item ID: 00848-2023-0016
Date Issued: 11/09/2023
Priority: Priority Repair
Deficiency: Hollow Concrete
Structural Component: Deck
Comments: - Isolated (intact) hollow areas. These locations are as follows:

- Span 1, west fascia parapet with (2) hollow areas on the outside face up to 3' long x 1' high over the right lane/shoulder near abutment 1.
- Span 2, east fascia parapet with hollow area on the outside face 6" long x 1' high over the right shoulder near abutment 2.

Date Completed: Actual Quantity:



Span 1, west parapet near abutment 1 with hollow area.

Form: Maintenance
Carried: ROUTE 89
Crossed: INTERSTATE 84

:Bridge No 00848

Town: UNION
Inventory Route: Non-NHS

Status: Bridge Maintenance Garage
Assigned To: District_1 Bridge
Work Item ID: 00848-2023-0015
Date Issued: 11/09/2023
Priority: Priority Repair
Deficiency: Hollow Concrete
Structural Component: Deck
Comments: Isolated intact hollow areas up to 2' x 1' with minor spalling over road. These locations are as follows:

- Span 1, 2' long x 1' wide hollow area over right lane in bay 4, panel 2.
- Span 2, 2' long x 10" wide dull/hollow area over left lane in bay 3, panel 3.
- Span 2 , adjacent to the 5' long x 3' wide x 4-1/2" deep (coated) spall there are (2) hollow areas up to 6" away over the right lane/shoulder in bay 3, panel 4.
- Span 2, 1' diameter hollow area over the slope protection/right shoulder in bay 3, panel 5.
- Span 2, 1' long x 7" wide hollow area over center lane in bay 5, panel 3.

Date Completed: Actual Quantity:



Span 2, bay 3, panel 3. Note spalls with exposed rebar and adjacent hollow areas.

Form: Maintenance
Carried: ROUTE 89
Crossed: INTERSTATE 84

:Bridge No 00848

Town: UNION
Inventory Route: Non-NHS

Status:	Bridge Maintenance Garage	Assigned To:	District_1 Bridge	Work Item ID:	00848-2019-0010
Date Issued:	12/31/2019	Priority:	Priority Repair		
Deficiency:	Welds/ Cracks				
Structural Component:	Superstructure				
Comments:	Top and overhead horizontal welds are cracks/broken between cross frame bottom angles and web stiffeners; some members are lifted up/rotated up to 2.5". One of two lower horizontal angles of cross frames supported by two square steel plates welded to the top of the angles. These locations are as follows:				
	Span 1:				
	- Bay 2, diaphragms 2, 3 & 6				
	- Bay 3, diaphragm 3				
	- Bay 4, diaphragm 3				
	- Bay 5, diaphragm 3				
	Span 2:				
	- Bay 4, diaphragm 3				
	- Bay 5, diaphragm 6				
	Repair broken cross frames ,clean and paint.				
Date Completed:		Actual Quantity:			



Span 1, bay 5, third intermediate diaphragm: Deformed/bent lower members and broken overhead welds due to impacted rust (rust removed).

Form: Maintenance
Carried: ROUTE 89
Crossed: INTERSTATE 84

:Bridge No 00848

Town: UNION
Inventory Route: Non-NHS

Status:	Bridge Maintenance Garage	Assigned To:	District_1 Bridge	Work Item ID:	00848-2019-0009
Date Issued:	12/31/2019	Priority:	Routine Repair		
Deficiency:	Steel Corrosion				
Structural Component:	Superstructure				
Comments:	Span 2, bay 1, diaphragm 4 has a 1' x 4" rusted through hole in the lower angle. Replace/repair the rusted-out diaphragm angle.				

Date Completed:	Actual Quantity:
-----------------	------------------



Span 2, bay 1, 4th diaphragm with a rusted through hole in the lower angle.

Form: Maintenance
Carried: ROUTE 89
Crossed: INTERSTATE 84

:Bridge No 00848

Town: UNION
Inventory Route: Non-NHS

Status: Bridge Maintenance Garage **Assigned To:** District_1 Bridge **Work Item ID:** 00848-2019-0008

Date Issued: 12/31/2019 **Priority:** Routine Repair

Deficiency: Welds/ Cracks

Structural Component: Superstructure

Comments: Overhead horizontal welds are cracked/broken between cross frame bottom angles and web stiffeners due to up to 3/4" impacted rust at the following locations:

Span 1:

- Bay 2, diaphragms 2, 4, 5 and 6
- Bay 3, diaphragms 2, 3, 4 and 5
- Bay 4, diaphragms 2, 3 and 5
- Bay 5, diaphragms 2, 3 and 5
- Bay 6, diaphragms 2 and 3

Span 2:

- Bay 1, diaphragm 4
- Bay 2, diaphragms 1, 3, 4, 5 and 6
- Bay 3, diaphragms 1, 2, 3, 4, 5 and 6
- Bay 4, diaphragms 4, 5 and 6
- Bay 5, diaphragms 3 and 5

Repair /clean and paint.

Date Completed: **Actual Quantity:**



Typical impacted rust between lower intermediate diaphragm members. Also, note and broken overhead weld (typical condition).

Form: Maintenance
Carried: ROUTE 89
Crossed: INTERSTATE 84

:Bridge No 00848

Town: UNION
Inventory Route: Non-NHS

Status: Bridge Maintenance Garage
Assigned To: District_1 Bridge
Work Item ID: 00848-2019-0007
Date Issued: 12/31/2019
Priority: Routine Repair
Deficiency: Steel Corrosion
Structural Component: Superstructure
Comments: The following locations along the superstructure has laminated rust and section losses:

- Span 1:
- Girders 1 & 3, panel 5, bottom flange
 - Girders 6 & 7, panel 2, bottom flange
 - Girder 1 web end at pier
- Span 2:
- Girders 1-7, random locations near mid-span, bottom flanges
 - Girder 1 web end at abutment 2
 - Girder 7 web end at pier

Clean and paint the affected areas.

Date Completed: Actual Quantity:



Span 2, girder 2, east elevation at panel 4: Laminated rust and section loss at bottom flange.

Form: Maintenance
Carried: ROUTE 89
Crossed: INTERSTATE 84

:Bridge No 00848

Town: UNION
Inventory Route: Non-NHS

Status:	Bridge Maintenance Garage	Assigned To:	District_1 Bridge	Work Item ID:	00848-2019-0006
Date Issued:	10/03/2019	Priority:	Priority Repair		
Deficiency:	Steel Corrosion				
Structural Component:	Superstructure				
Comments:	There is up to +/-2" thick impacted rust between the back to back angles of the lower members at the intermediate diaphragms (this condition is typical throughout both spans). Large areas of rust will fall into the roadway from these locations. Baker crew removed some of these areas, but not all (see attached photos).				

Date Completed:	Actual Quantity:
-----------------	------------------



Typical impacted rust between the components of the lower intermediate diaphragm member.