

Appendix G

Soil Corrosivity Results and Corrosion Evaluation Report

Client Stantec Consulting
Project MWRA WASM 3 Corrosion Exposure
Job No. 9301

No.	Boring	Pipe Section	Soil Resistivity: Laboratory	Moisture Content	Chloride Salinity	pH Value	Sulfides	Redox Potential	Corrosivity Index	Corrosivity Category	Corrosion Rate	Soil Classification	Historical Leak	Stray Current TS MWRA ID	Stray Current TS Sta. No.	Concrete encased	Closest Address	Notes
			(Ω-cm)	(%)	(PPM)		(L/M/H)	(mV)			(Mils/Yr)							
1	B-2	9	52000	5.5%	<31	5.81	Low	221.6	4	Non-Corrosive	1.57	Sand and Gravel, trace silt		W9-2-A	10+10	No	58 River Rd	"Very dense sand & gravel"
2	B-5	9	67000	8.1%	<31	6.43	Low	301.3	4	Non-Corrosive	0.30	Sand and Gravel, trace silt	1			No		
3	B-7	9	140000	3.7%	<31	6.60	Low	304.6	4	Non-Corrosive	0.45	Sand, some gravel, little silt				No		
4	B-9	9	9400	16.1%	<31	6.78	Low	275.2	0	Non-Corrosive	2.82	Sand, some silt, little gravel				No		Cambridge W.W. 36-in CI Pipe
5	B-11	9	23000	11.0%	<31	7.34	Low	253.9	2	Non-Corrosive	1.05	Sand & Gravel, trace silt				No		
6	B-13	9	130000	3.9%	<31	5.72	Low	330.8	4	Non-Corrosive	0.60	Sand and Silt, trace gravel		W9-12-A	78+15	No	Howe Ave/Maynard Ave	WASM3 running through cemetary
7	B-17	9	66,000	2.0%	86	8.70	Low	213.1	4	Non-Corrosive	9.80	Sand & Gravel, trace silt	1	W9-13-D	84+10	No	Howe Ave/Riverview Ave	WASM3 running through cemetary , then crosses RR. Good spot for pipe calibration, 545-ft
8	B-20	9	24000	14.0%	<31	7.05	Low	303.9	2	Non-Corrosive	3.85	Fine Sand, trace med. Sand, trace silt				No		WASM3 parallel w/ RR
9	B-23	9																WASM3 parallel w/ RR
10	B-24	9	13,000	10.5%	18	6.32	Low	269.0	-4	Moderately-Corrosive	8.17	Sand, some gravel, some silt	8	N/A	Leak Location	No	Bellevue St/Prospect St	WASM3 parallel w/ RR
11	B-27	10	71,000	5.0%	4	7.35	Low	215.1	4	Non-Corrosive	2.21	Sand & Gravel, little silt	1	W10-9-A		No	103 Felton St	WASM3 parallel w/ RR
12	B-29	10	8,800	12.3%	52	7.72	Low	274.1	0	Non-Corrosive	2.25	Sand & Gravel, trace silt	7	W10-11-G	148+07	No	Felton St/Moody St	WASM3 parallel w/ RR
13	B-29	10	7,000	2.1%	29	9.48	Low	168.0	2	Non-Corrosive	0.20	Gravel fill	7	W10-11-G	148+07	No	Felton St/Water St	W10-10 Leak Location (10/1/18): East end of excavation
14	B-29	10	7,200		29	8.70	Low	187.0	0	Non-Corrosive	0.45	Clay	7	W10-11-G	148+07	No	Felton St/Water St	W10-10 Leak Location (10/1/18): West end of excavation
15	B-29	10	59,000	11.3%	29	8.51	Low	287.0	4	Non-Corrosive	0.44	Gravel fill	7	W10-11-G	148+07	No	Felton St/Water St	W10-10 Leak Location (10/1/18): Center end of excavation
16	B-31	10	1,100	10.6%	165	6.95	Low	324.9	-6	Corrosive	6.35	Sand, some silt, trace gravel		1		No	Moody St/Felton St	WASM3 parallel w/ RR
17	B-32	10	63000	7.1%	<31	7.60	Low	250.7	4	Non-Corrosive	0.26	Sand & Gravel, trace silt	2	W10-13-A	159+00	No	86 Central St	WASM3 parallel w/ RR
18	B-35	10	4,500	16.4%	128	8.38	Low	233.0	-2	Moderately-Corrosive	4.29	Sand & Gravel, trace silt	1	W10-14-A	169+90	No	Central St/Newton St	WASM3 parallel w/ RR
19	B-38	10	42,000	8.7%	4	8.93	Low	172.0	2	Non-Corrosive	3.48	Sand, trace silt	1			No		WASM3 parallel w/ RR
20	B-39	10	120,000	4.5%	6	9.05	Low	215.1	6	Non-Corrosive	0.45	Sand, trace silt	1			No		WASM3 parallel w/ RR
21	B-41	10	40000	8.8%	<31	7.32	Low	273.4	2	Non-Corrosive	1.53	Sand & Gravel, trace silt	1			No		WASM3 parallel w/ RR
22	B-42	10	5,600	37.6%	8	5.85	Low	158.2	-1	Moderately-Corrosive	11.50	Organic Silt, some gravel	8	W-10-24-A	201+75	No	Linden St/Waverly Oaks Rd	WASM3 parallel w/ RR, pipe invert dips to ~14-ft, under Beaver Brook Culvert
23	B-43	10	11,000	10.8%	4	7.25	Low	304.1	0	Non-Corrosive	5.19	Sand & Gravel, little silt				No		WASM3 parallel w/ RR
24	B-46	10	36000	15.9%	<31	6.87	Low	329.4	2	Non-Corrosive	0.29	Silt	2	W10-26-A	233+10	No	Waverly Oaks Rd/Beaver St	
25	B-48	10	10,000	5.8%	10	6.57	Low	343.0	0	Non-Corrosive	1.17	Sand, little silt				No		
26	B-50	10	14,000	11.6%	6	8.58	Low	268.0	0	Non-Corrosive	1.31	Sand & Gravel, little silt	1	W10-28-B	247+30	No	Waverly Oaks Rd/Chapel Rd	
27	B-52	10																No sample taken, refusal due to bolder
28	B-55	11	32,000	8.3%	6	7.17	Low	318.2	2	Non-Corrosive	1.58	Sand & Gravel, trace/little silt				No		
29	B-58	11	270,000	3.1%	15	7.38	Low	250.4	3	Non-Corrosive	0.39	Sand & Gravel, trace silt	1			No		
30	B-62	11	130000	5.8%	<31	6.60	Low	290.8	4	Non-Corrosive	0.32	Sand & Gravel, little silt				No		
31	B-64	11	18000	7.9%	<31	6.66	Low	243.1	2	Non-Corrosive	2.08	Silt, little gravel, trace sand	1			No		
32	B-66	11	260	29.5%	226	6.75	Low	289.0	-9	Corrosive	13.60	Silt, trace sand		W11-7-A	310+90	No	900 Pleasant St	
33	B-69	11	12,000	7.2%	77	5.81	Low	315.0	0	Non-Corrosive	0.67	Sand, some silt, trace gravel				No		
34	B-71	11	59,000	8.8%	20	8.16	Low	222.5	4	Non-Corrosive	0.91	Sand, little gravel				No		
35	B-72	11	1,030	13.5%	68	7.18	Low	244.1	-6	Corrosive	14.50	Sand & Gravel, little silt	1	W11-12-A	344+70	No	628 Pleasant St	
36	B-75	11	7700	16.6%	<31	6.81	Low	301.1	0	Non-Corrosive	4.57	Sand & Gravel, little silt	1			No		
37	B-78	11	10,000	13.2%	68	8.55	Low	224.0	0	Non-Corrosive	2.09	Sand, little silt	2	59-28-A	349+90	No	Pleasant St/Alexander Ave	
38	B-79	11	15,000	4.3%	68	7.76	Low	217.3	0	Non-Corrosive	3.14	Sand, some gravel, trace silt				No		
39	B-81	11	18,000	7.8%	8	7.02	Medium	250.1	-3	Moderately-Corrosive	1.60	Gravel, little sand	1			No		Leak at pipe near this boring 3/21/18, photos to be received
40	B-82	11	3,800	9.1%	16	9.10	Low	202.8	0	Non-Corrosive	9.31	Sand, some gravel, little silt		W11-17B-B	391+85	No	Concord Trnpg/Venner Rd	
41	B-84	11	14,000	15.0%	31	7.38	Low	249.1	0	Non-Corrosive	0.85	Sand, little gravel, trace silt	1			No		
42	B-85	11	26,000	8.2%	15	6.81	Low	304.6	0	Non-Corrosive	0.37	Sand & Gravel	1			No		
43	B-88	11	12,500	8.1%	18	6.68	Medium	372.0	-3	Moderately-Corrosive	1.60	Sand, little gravel		W11-22-A		No	87 Pleasant St (Arlington)	OR excavate in the yard of 135 Pleasant St
44	B-91	11	6,900	9.2%	17	7.83	Low	262.3	0	Non-Corrosive	2.29	Sand, little gravel				No		
45	B-93	11	74,000	5.5%	9	9.00	Medium	205.5	-3	Moderately-Corrosive	0.08	Sand & Gravel	1			No		
46	B-94	12	8,300	6.9%	9	9.37	Medium	183.0	-1	Moderately-Corrosive	4.53	Sand, some gravel, little silt	1	W12-2-A	445-65	No	Broadway/Alton St (Arlington)	
47	B-97	12	34,000	5.8%	9	7.47	Low	258.8	0	Non-Corrosive	2.94	Sand, some gravel, trace silt	1	W12-4-A	462+40	No	Palmer St/Warren St (Arlington)	
48	B-98	12	6,600	9.0%	21	8.01	Low	239.0	0	Non-Corrosive	1.00	Sand, some gravel				No		
49	B-100	12	130,000	3.7%	9	8.40	Low	219.5	0	Non-Corrosive	0.23	Sand, trace silt		W12-7A-A	487+50	No	152 Mystic Valley Pkwy (Arlington)	approx 1700-ft PCCP Calibration
	B-101															No	Coral St @ Park St (Arlington)	
50	B-103	12	1300	25.7%	<31	4.74	Low	268.5	-6	Corrosive	25.50	Wet compacted mud	2	W12-8B-B	504+45	No	22 Mystic Valley Pkwy	26-in Steel Gas Pipe crossing
51	B-105	12	5,200	12.7%	9	7.39	Low	27.3	-6	Corrosive	8.28	Sand & Silt, little gravel	1	W12-10-K	510+34	No	Mystic Valley Pkwy/Capen St	WASM3 crosses a 43-in sewer line just west of valve, and then crosses a blue line twice just e
	B-107																Irvington Rd (Medford)	
52	B-108	16												W16-1-B	521+14	Yes	Boston Ave/Mide Tech. Corp	NO corrsivity sample taken at this location, not sure why
53	B-109	16	920	20.0%	31	7.87	High	339.9	-12	Very Corrosive	2.71	Sand & Gravel, little Organic Silt				Yes	No Access	WASM3 crosses RR
54	B-110	16	1200	34.5%	<31	4.74	High	232.8	-12	Very Corrosive	19.80	Wet compacted mud	1			Yes	Auburn St @ Whole Foods (Medfor	"Clayey Peat"
55	B-112	16	8800	14.5%	<31	4.23	High	320.0	-7	Corrosive	7.12	Wet gravel		W16-12-A		Yes	Mystic Valley Pkwy/Winthrop St	
56	B-113	16	370	57.6%	<31	6.51	High	-20.1	-18	Very Corrosive	29.50	Wet compacted mud		W16-13-A		Yes		WASM3 crosses 6-in oil line w/10-in sleeve, then parallel w/8.5-ft MWRA sewer
57	B-115	16												W16-13A-B	557+19	Yes	2500 Mystic Valley Pkwy	
Minimum			260	2.00%	4	4.23		-20.1	-18		0.08	Total Leaks	71					
Maximum			140000	57.60%	226	9		372.0	6		29.50							
Average			37552	11.82%	37	7		251.1	-1		4.37							

≥ 0	Non-Corrosive
-1 to -4	Moderately-Corrosive
-5 to -10	Corrosive
< -10	Very Corrosive

**Corrosion Evaluation Report
Weston Aqueduct Supply Main 3 (CP2)
Massachusetts Water Resource Authority**

Prepared for:

**Stantec Consulting Services Inc.
65 Network Drive
Burlington, MA 01803**

Prepared by:



**CorrTech Inc.
25 South Street
Hopkinton, MA 01748
Report No. 9301-FOR-03-3**

April 2023

STATEMENT OF LIMITATION

The conclusions presented in this document are based on the services described and not on tasks or procedures beyond the scope of the described procedures or the time and budgetary constraints imposed by the contract limitations.

CorrTech, Inc. has performed this assessment in a professional manner using that degree of skill and care exercised for similar projects under similar conditions by reputable and competent consultants, and in accordance with the procedures established within CorrTech's quality assurance, quality control protocol.

CorrTech, Inc. shall not be responsible for conditions or consequences arising from relevant facts that were concealed, withheld or not fully disclosed at the time the evaluation was performed.

Report Prepared By:



Max Mizejeski
Project Engineer

Report Reviewed By:



Scott Paul, PE
Technical Director
NACE Corrosion Specialist No. 4163

TABLE OF CONTENTS

Introduction	1
Executive Summary	1
Discussion and Conclusions	7
Recommendations	10

APPENDIX I

Pipe Measurement Charts

APPENDIX II

Coating Thickness Logs

APPENDIX III

Soil Resistivity Measurements

APPENDIX IV

Photo Log

APPENDIX V

Pipe Test Pit As-built Drawings Waverly Oaks Road

Introduction


Under Contract No. 6539 for the design, construction administration, and resident inspection services of the Weston Aqueduct Supply Main 3 (WASM-3), hereinafter called the "Project", awarded to Stantec by Massachusetts Water Resource Authority (MWRA), CorrTech has been tasked with the condition assessment and corrosion control development for the rehabilitation of the water main.

This report, 9301-03-1, details the findings of CorrTech's direct pipe assessment of the WASM-3 CP-2 along Waverly Oaks Road in Waltham, MA. Data from a previous report, 9301-2-3, produced in 2021 is included, Site #3 from that report was located at Sta. 227+50 and will be referred to as Site #3 (2021 designated) within this report.

Executive Summary

Between the days of March 16th, 2023, and March 21st, 2023 CorrTech personnel were onsite to perform pipeline integrity evaluations at five excavation sites along Waverly Oaks Road between station 205+28 and 235+00, from Linden St to Beaver St, approximately 2,972-ft as part of the CP2 limit of work. These sites are denoted herein as follows:

- Site #1: Sta. 205+28 Int. of Linden St. and Waverley Oaks Rd
- Site #2: Sta. 214+00, 56 Waverley Oaks Road
- Site #3: Sta. 217+17 68 Waverley Oaks Road
- Site #4: Sta. 220+85 79 Waverly Oaks Road
- Site #3 (2021 designation): Sta. 227+50 79 Waverly Oaks Road
- Site #5: Sta. 229+85 191 Waverly Oaks Road



Through a series of systematic tests and evaluations including pit depth measurements, A- and B-Scan readings, and coating thickness measurements in addition to the prior leak history of the system under evaluation, conclusions and recommendations can be made.

Excavation typically exposed 60-70% of the pipe in the test pit with portions still being completely buried due to site restrictions such as other pipelines and pipe support. Measurements were taken at the crown, one side of the spring line and as close to the invert as possible.

Corrosion Pits

Steel, or iron pipe including cast iron, corrodes when buried as a result of several major factors. The primary factor for these conduits is corrosion due to soils. This type of corrosion on steel pipes typically results in pitting of the steel surface and is particularly vicious when initiated in areas of coating faults. Of concern would be pitting activity that would lead to through-wall penetrations, resulting in loss of structural integrity and product.

When steel pipe corrodes in most soils, the resulting loss of metal is far from uniform. Generally, there tends to be small areas of metal loss (pits) in larger areas of uncorroded or lightly corroded metal surface. The depth of pits will vary greatly. Usually there will be far greater numbers of shallow pits than deep pits. As pit depth decreases, the number of pits increases. As pit depth approaches zero, the number of pits approaches infinity. This is in agreement with the theory of extreme value probability.

Pitting corrosion initiates on the steel surface at points where coating holidays exist in the external coating and soil and water conditions provide electrochemical conditions to support corrosion. These sites are typically initiated in the presence of the chloride ion. Once initiated, the corrosion rate of a corrosion pit is aggressive due to the autocatalytic nature of the chemistry within the pit. That is, the corrosion processes within an active pit produce conditions which are stimulating and contribute to continual corrosion activity within the pit.

In the industry literature, pitting rates are reported to vary for different materials and environments. Under some conditions, pit rates increase over time and in others, pit rates decrease with time. In soil, the pit growth rate tends to decrease with time and generally follows a power equation $P = kt^n$, where P is the depth of the deepest pit in time t , and k and n are constants. Where soils are well aerated, n is low in the range of 0.1, and where soils are not well aerated, n is higher in the range of 0.9. Therefore, in clay and fine-grained soils n is higher and the pit rate is greater than for sandy and large grain size soils. Where soils are not well aerated, and n approaches 1, the penetration rate is directly proportional to time.

Corrosion pits penetrate the pipe wall at a certain corrosion rate, primarily due to the corrosion mechanism associated with the pit geometry and pit depth. Corrosion mechanisms that tend to increase the diameter of the pit are not as aggressive as those that tend to increase the depth and therefore pits tend to be deep and narrow. The environment at the bottom of a pit is much more acidic than that at the surface, and therefore more corrosive.

It should be noted that through wall pits cause leaks, but structural integrity is not substantially compromised until the density of pits is very high (i.e. a pipe will not fail catastrophically until pitting has removed a substantial portion of the pipe.) Additionally, some rehabilitation methods

(ex. cement mortar lining) may allow a pipe with through wall pits to remain in useful service, as the leaks will be stopped by the rehabilitation method.

For this analysis, the time to failure is considered to be at a time when the corrosion hole is large enough in diameter that the cement mortar lining is compromised. This compromise considers internal pressure, lining thickness and corrosion hole diameter.

It is considered that there are many areas along Waverly Oaks Rd conduits where the soils consist of clay and fine-grained material, specifically the pipe bedding material. These soil conditions were observed in a large percentage of the soil samples obtained during the study.

Of interest, is the diameter of the corrosion hole that would no longer provide support to the internal mortar lining system. Based on an analysis performed by CorrTech on a previous project, CorrTech has utilized a hole size failure of 0.50-inch diameter, with the internal lining thickness of 0.25-inch at 1,000 psi strength. This size hole would fail at an internal water pressure of 132 psi.

The tables for the cement mortar lining "blowout" pressures were prepared using the "strength-design" method from the "Building Code Requirements for Structural Concrete", ACI-318-02 prepared by the American Concrete Institute. Specifically, Chapter 22, "Plain Structural Concrete". With the "strength-design" method a margin of safety is provided by multiplying the design loads by a load factor and the member capacity by a strength reduction factor.

Load factors are assigned based on the degree of accuracy that the loads can be calculated. The more accurate and less variable the load the smaller the load factor. Load factors also account for variability in the structural analysis used to compute the moments and shears. The load factor used in our analysis was 1.4 for well-defined fluid pressures with liquids of known density.

Strength reduction factors are to allow for the probability of understrength due to variations in material strengths and dimensions, to allow for inaccuracies in the design equations, to reflect the degree of ductility and required reliability of the member under load and to reflect the importance of the member in the structure (the latter is really intended for beam/column structures). The strength reduction factors used in our analysis ranged from 0.75 to 0.9 depending on the failure mode.

The tables without the safety factors use 1.0 for both the strength reduction factor and load factor but should be used with caution since there can be in-place variability of lining thickness, concrete strength and pressures.

This discussion indicates that cleaning and lining a steel water main such as WASM 3 provides the following characteristics:

- Improved C factor
- Steel passivating environment with the mortar lining and pH of approximately 12
- Internal pressure withstand capacity to bridge external large diameter holes with two layers of ½-in thick each layer mortar lining, applied in 2 passes for 1-in total

Pipe Evaluation

In order to perform a thorough and detailed analysis, the investigating engineers on-site started by creating a grid system on the exposed portion of each pipe. The deepest pit due to exterior corrosion in each grid section was measured and recorded. Pipe wall thickness was also measured in each section using an A-Scan measurement technique with an ultrasonic thickness gage and transducer. Site #1 had a nominal wall thickness of 0.500-in while Sites #2-5 had a nominal wall thickness of 0.375-in, complete results of both measurements can be found in Appendix I.

Pipe wall thickness was also measured using a B-Scan measurement technique when possible, the B-Scan method requires a very smooth surface, any obstructions uneven surfaces or poorly adhered coating can cause inaccurate readings. Typically, the surface would be prepared with an angle grinder but due to field concerns related to aggressive tool preparation it was decided to prepare the surface using hand tools. B-Scans were performed at Sites #2 and #4. Plots of this data can be found in Appendix I with the corresponding pipe measurement chart. Additionally, coating thickness readings were taken at various positions on the exposed portions of pipe and data summarized in Appendix III.

Overall, the pipe was found to be structurally sound with no significant issues. All portions of the lockbar that were observed were free from significant pitting or metal loss. The coating was approximately 50% delaminated but where it was still adhered there was at least 20-mils of coating remaining. Pitting was generally sporadic and did not compromise the pipes integrity.

Statistical Analysis

The present state of technology offers no other practical way of determining corrosion pit depths on operating underground piping systems other than direct physical examination of the pipe surface. This, of course, requires the excavation of the pipe, an expensive procedure. This leads us to attempt to find a way of predicting the nature of pitting for the entire structure with the excavation and examination of only a small portion of the structure. This presents a difficult problem, both from a practical and theoretical standpoint. The pits of greatest interest are the deeper ones, yet these are the pits that occur most rarely. The probability of finding the deepest pit, on a mile of pipe, by randomly inspecting only one percent of the pipe would be very small.

For this study, six test pit excavations were evaluated along Waverley Oaks Road, Waltham, MA to determine from a practical approach, the corrosion activity along the pipe route. Inspection of 1% of the pipe surface is considered ideal for the statistical analysis. Test pits on Waverley Oaks provided approximately 0.78% of the pipe for inspection. Data analysis indicates that the line of expected extremes is reasonably valid for the size of our pipe sample. This indicates that the data generally agrees with the extreme probability theory. Therefore, this evaluation of approximately 0.78% of the pipe surface is considered to be an acceptably accurate analysis.

In analyzing extreme values encountered in statistical samples, the deepest pit in the pipe is of concern. Gumbel's method of analysis to pit depth data has been utilized to evaluate the data. This method of analysis, together with studies of factors influencing the corrosion of the structure of concern, such as soil resistivity and soil moisture content, allows prediction of the magnitude of corrosion penetration problems that will be encountered on a given structure. This can be done by inspecting only a very small portion of the structure.

Once the unit of study has been established, locations can be selected for physical examination of the pipe surface. For this study, the statistical unit of one-square foot was selected based on maximizing the accuracy of the statistical analyses and this size unit is preferred based on experience in applying extreme values statistical analysis. Ideally, a sufficient number of locations are selected to be representative of the corrosion conditions affecting the structure throughout the study area. The size and number of inspection locations will vary with the length of the structure, the nature of the corrosion conditions to which it is subjected and cost considerations.

The pipe must be excavated at one (1) or more locations, with ten linear feet of pipe available for inspection at each location. The size of each statistical unit is further reduced by dividing the pipe within the excavation into small statistical units. Therefore, a ten-foot long excavation can lead to the division of the pipe within this excavation into one hundred and forty (140)-one (1) square foot sections, for a 60-in diameter pipe. In this study, a statistical unit of one square foot was used. The size of the statistical unit is chosen such that each excavation theoretically results in approximately 140 statistical units for each pipe in an excavation.

Having established the size of the statistical unit, the depth of the deepest pit in a given statistical unit is measured and recorded. In practice it is necessary to actually measure a number of the apparently deepest pits. Based on the excavation limits, the test pits did not allow evaluation of 140 statistical units. The number of statistical units available ranged from 34 at Site #1 up to 103 at Site #5. Across 6 sites and with 140 units there was a potential maximum of 840, of which 364 were measured, or approximately 0.78% of the statistical units

If the above conditions are satisfied, we can then utilize the graph in predicting the nature of corrosion pits on the portion of the structure outside of the area inspected. If, as previously stated, our first interest is in the possibility of corrosion penetrations existing on the structure, the best fit equation is used to calculate the percentage of statistical units along the pipe where these conditions would be expected.

By a similar analysis, a prediction can be made, with a relatively high correlation, regarding the total number of penetrations that will occur by some future date. The number of pits to a given depth that exist on the entire structure is determined using the extreme probability graphs. The annual corrosion rate is calculated by dividing the pit depth by the age of the pipe. An assumption is made that the corrosion rate is linear (i.e. a pit of 0.1 inches in ten years will progress to 0.2 inches in 20 years). Much of the literature suggests that pitting may actually slow over time. In addition, corrosion on the pipe under study has been heavily influenced by stray currents, that have been reduced over time. Therefore, assuming a linear rate is conservative. This rate is typically expressed in mils (0.001 inches) per year.

The depth of the existing pits is subtracted from the wall thickness to yield the remaining thickness. The remaining thickness is then divided by the corrosion rate to yield the number of years to penetration. Since the rate of corrosion is not a linear function of time and the wall thickness is not absolutely uniform, adjustments must be made. Specifically, the analysis would deal with a range, or band of time.

Test Sites	Thinnest Wall Thickness Measured	Nominal Pipe Wall	A-Scan Thickness Measured
Site #1	0.270-in external pit	0.500-in	0.450-in to 0.550-in
Site #2	0.129-in external pit	0.375-in	0.334-in to 0.407-in
Site #3	0.245-in external pit	0.375-in	0.345-in to 0.390-in
Site #4	0.121-in external pit	0.375-in	0.332-in to 0.392-in
Site #3 (2021 site 3)	0.070-in B scan	0.375-in	0.297-in to 0.394-in
Site #5	0.305-in external pit	0.375-in	0.350-in to 0.393-in

Soil Resistivity

CorrTech evaluated the soil in each test pit by measuring soil resistivity at the pipe invert, springline and crown.

The measurement of soil resistivity has been used for years as an indicator of the corrosivity of soil. Soil resistivity is the reciprocal of conductivity, the lower the resistivity, the easier current will flow through the soil. Of the measurable soil characteristics, resistivity is generally accepted as the primary indicator of soil corrosivity. Resistivity is a property of the bulk volume of soil and electrolytes.

Although no standard has been developed and accepted by such organizations as the American Society for Testing and Materials or the National Association of Corrosion Engineers, it is generally agreed that the classification shown below, or other similar classifications, reflect soil corrosivity.

Resistivity (Ohm-Cm)	Corrosivity
below 500	Very Corrosive
500 to 1,000	Severely Corrosive
1,000 to 2,000	Moderately Corrosive
2,000 to 10,000	Mildly Corrosive
Above 10,000	Progressively Less Corrosive

The above Table provides qualitative insight to the expected corrosion exposure of a metallic structure in a soil of known resistivity. Accordingly, deterioration can generally be expected to be rapid and relatively severe in soils below 1,000 ohm-cm. This does not mean, however, that severe corrosion will not occur in soils of higher resistivities. In fact, depending on chemical conditions, severe corrosion can occur in soils above 10,000 ohm-cm. The Table only indicates that the latter occurrence is generally not observed.

Not only is the resistivity useful in predicting relative corrosion rates, but it is equally important to identify whether soil resistivity varies along a given route. Structures such as pipes, which are electrically continuous along significant portions of their length, will be susceptible to long line galvanic influences arising from variations in soil resistivity and moisture along the pipe route. Portions of a pipeline in the lower soil resistivity environments tend to become anodic, and therefore corrode, relative to other portions of the same pipeline. Resistivity data are summarized in Appendix I.

Discussion and Conclusions

Various forms of statistical analysis were used to analyze the data collected and determine the best course of action to mitigate the corrosion taking place and eliminate the risk of leaks to the pipeline.

External pitting was found to be infrequent with only 118 of the 364 statistical units having any pitting and 98 of the 118 being less than 1/3 of the design thickness or 20 pits greater than 120 mils. The following table summarizes the pits measured:

Quantity	Pit Depth, Mils
246	0
22	10
13	20
9	30
3	40
10	50
9	60
9	70
3	80
3	90
8	100
7	110
2	120
3	130
2	140
4	150
4	160
1	170
3	180
1	190
1	200
1	210
364	Total statistical units


Based on the extreme statistical analysis, there are expected to be 47 through holes in the pipe between Linden and Beaver St. There have been sixteen 16 leaks since 1991 in this pipe segment as summarized:

WASM 3 - CP2 Leak Locations				
4/12/2023				
STA. 205+00 to 235+00				
Leak Year	Approx. S	Street Name		
1991	207+50	Linden St @ Waverly Oaks Rd		
2011	207+50	Linden St @ Waverly Oaks Rd		
2007	207+50	Linden St @ Waverly Oaks Rd		
1996	207+50	Linden St @ Waverly Oaks Rd		
2009	207+50	Linden St @ Waverly Oaks Rd		
2011	207+50	Linden St @ Waverly Oaks Rd		
2019	207+50	Linden St @ Waverly Oaks Rd		
2022	207+50	Linden St @ Waverly Oaks Rd		
1989	207+50	Linden St @ Waverly Oaks Rd		
2003	207+50	Linden St @ Waverly Oaks Rd		
2022	212+00	Waverly Oaks Rd		
2022	212+00	Waverly Oaks Rd		
2016	222+00	Waverly Oaks Rd		
2018	222+00	Waverly Oaks Rd		
2006	222+50	Waverly Oaks Rd		
2005	233+00	Waverly Oaks Rd @ Beaver St		

It is considered that an additional seven 26 external leaks will manifest within the next approximately 25-year time frame.

The following graphical assessment is presented:

Frequency of Through Hole	0.001016621
Area of Pipe (ft.^2) statistical units	46,660
Number of leaks	47



A-Scan and B-Scan ultrasonic thickness (UT) measurements were taken to evaluate the interior condition of each exposed portion of pipe. A-Scan measurements provide pinpoint spot readings of the remaining wall thickness at any given location on a pipe. A-Scans were sometimes difficult to acquire due to poor coating adhesion or uneven surface profile and were not collected for every statistical unit. B-Scan measurements, however, provide a profile of wall thickness readings over a given distance. In combination, these two non-destructive measurement techniques can be invaluable in assessing the condition of pipelines. As previously mentioned, B-Scans were only able to be taken from Sites 2 and 4. Scans conducted in March of 2023 revealed internal pits where the wall thickness was 0.121-in or a pit depth of 254-mils. Scans conducted in May of 2021 revealed thicknesses as low as 0.070-in or a pit depth of 305 mils. Typically, the steel thickness would decrease the closer to the 6'o'clock position they were taken.

Considering a 305-mil internal pit and 100-years of operation, assuming corrosion initiated on day one of operation, the calculated linear corrosion rate is 3.05 mils per year. For a 375 mil thick steel pipe, penetration of the existing 305-mil pit would take approximately 22 years.

The coating on the exterior of the pipe trended similar to the UT readings, coating was thinner towards the bottom of the pipe with most of the coating being delaminated below the spring line. At the crown the coating was typically between 30-60-mils, 20-30-mils near the spring line and

20 mils down to bare steel below that point. Coating thickness were collected for a general understanding and not necessary for each statistical unit.

It should be noted that through wall pits cause leaks, but structural integrity is not substantially compromised until the density of pits is very high (i.e. a pipe will not fail catastrophically until pitting has removed a substantial portion of the pipe.) Additionally, some rehabilitation methods (ex. cement mortar lining) may allow a pipe with through wall pits to remain in useful service, as the leaks will be stopped by the rehabilitation method.

Recommendations

With this new information and considering the existing plans to replace and line portions of the pipeline under survey, CorrTech recommends the following:

1. Consider internal cleaning and lining of the pipes from Linden to Beaver. cleaning and lining a steel water main such as WASM 3 provides the following characteristics:
 - Improved C factor.
 - Creates a steel passivating environment with the mortar lining and pH of approximately 12.
 - Provides a pressure withstand capacity to bridge external large diameter holes with the two layers of ½-in thick mortar lining each applied in two passes.
2. Design and install appropriate cathodic protection systems to all newly replaced portions of pipeline to protect from external corrosion and extend the usable life of these systems.

APPENDIX I
Pipe Measurement Charts

Test Site #1

West

	9	10	11	12	13	14	15	1	2	3	4	5	6	7	8	
A							0	0	0	0	0	0				
								520		550	470					
B							0	0	50	0	150	0				
								536	535	450	480					
C							0	30	0	0	200	0				
								520	519	511	490	470				
D							0	20	50	0	0	0				
								535	526	498	485					
E							0	0	0	0	150					
								514	506	512	477					
F							0	0	0	0	0					
								504	503	540						

Invert

Crowm

Invert

East

Key
Pit Depth Measurements (mils)
Ultrasonic Thickness (mils)
Coating Thickness (mils)
Buried Pipe

Deepest Pit: 200

Lowest UT: 450

Design Thickness : 0.500-in

Location: Sta. 205+28

Date: 23-Mar-23



Test Site #2

West															
9	10	11	12	13	14	15	1	2	3	4	5	6	7	8	
					50	50	10	10	160	110	70				
					391	362	367	368							
					20	30	30	30	20	15	5				
					50	40	10	10	40	100	130	70			
					382	394	389	390	377						
					20	20	30	30	20	15	5	8			
					70	30	10	30	170	110	140	160			
							400	407				387			
					20	20	30	30	20	15	5	8			
					50	70	10	10	210	160	90	50			
								384		396		383			
					20	20	30	30	20	15	5	8			
					30	30	10	10	140	100	50	30			
					20	20									
					30	20	10	10	160	110	180	60			
												334			
					20	20									
					20	20	10	10	130	150	70	190			
										375					
					20	20									
					20	20	10	10	100	150	180				
					20	20									
Invert					Crown									Invert	

Key	
Pit Depth Measurements (mils)	
Ultrasonic Thickness (mils)	
Coating Thickness (mils)	
Buried Pipe	

Deepest Pit: 210
 Lowest UT: 334
 Design Thickness : 0.375-in

Location: Sta. 214+00
 Date: 16-Mar-23



Test Site #3

West

	9	10	11	12	13	14	15	1	2	3	4	5	6	7	8
A						0	0	0	0	0	0				
							345								
											25				
B						0	0	0	0	0	0	130	0		
								345							
											30				
C						0	0	0	0	0	110	110	0		
							359			345					
							15				26				
D						0	0	0	0	0	100	80	0		
						381			345	361		367	390		
							36				35	23			
E						0	0	60	0	0	100	0	0		
								363							
							32				24	30			
F						0	0	0	0	0	0	0	0		
						351						370			
								20			30	35			
G						0	0	0	0	0	0	0	0		
									377		370				
											35				
H						0	120	0	0	0	0				
								382							
							45								

Invert

Crown

East

Invert

Key	
Pit Depth Measurements (mils)	
Ultrasonic Thickness (mils)	
Coating Thickness (mils)	
Buried Pipe	

Deepest Pit: 130
 Lowest UT: 345
 Design Thickness : 0.375-in

Location: Sta. 217+17
 Date: 23-Mar-23



Test Site #4

West															
	9	10	11	12	13	14	15	1	2	3	4	5	6	7	8
A						0	0	0	0	0	0	0			
						369	380				376				
						30	53								
B						0	0	0	0	0	0	0			
						343	355				372				
						28	32								
C						0	0	0	0	0	0	0			
						387	389				382				
						40	30	70							
D						0	0	0	0	60	0	60	110		
						376	348				375				
						41	29								
E						0	0	0	0	0	0	80	110		
						392	392				374				
						28	35								
F						0	0	0	0	90	0	100	180		
						395	390				344				
						31	29								
G						0	0	0	0	0	0	100	90		
						382	389				332				
						36	26								
H						0	0	0	0	0	0	100	60		
						372	365					379			
						32	32								
I						0	0	0	0	0	0	80	0		
						388	377					368			
						41	48								
Invert						Crown						Invert			
East															

Key	
Pit Depth Measurements (mils)	
Ultrasonic Thickness (mils)	
Coating Thickness (mils)	
Buried Pipe	

Deepest Pit: 180
Lowest UT: 332
Design Thickness : 0.375-in

Location: Sta. 220+85
Date: 16-Mar-23









Test Site #3 (2021 designation)

Pit Depth Measurements (mills)								
A1	B1	C1	D1	H1	I1	J1	K1	L1
10	20	.	10	10	20	20	10	30
A2	B2	C2	D2	H2	I2	J2	K2	L2
70	.	.	30	10	60	50	.	10
A3	B3	C3	D3	H3	I3	J3	K3	L3
.	.	60	60	.	.	70	20	.
A4	B4	C4	D4	H4	I4	J4	K4	L4
10	20	40	120	60	70	20	20	.
05/19/2021 - Sta. 227+50								
A-Scan Thickness Measurements (mills)								
A1	B1	C1	D1	H1	I1	J1	K1	L1
362	375	384	394	374	352	379	360	376
A2	B2	C2	D2	H2	I2	J2	K2	L2
351	377	387	360	375	350	380	372	372
A3	B3	C3	D3	H3	I3	J3	K3	L3
362	373	373	297	372	373	355	369	365
A4	B4	C4	D4	H4	I4	J4	K4	L4
367	379	388	371	312	358	373	373	355

Deepest Pit: 120
 Lowest UT: 297
 Design Thickness : 0.375-in

Test Site #3 (2021 designation) B-Scans



Test Site #5

	West														
	9	10	11	12	13	14	15	1	2	3	4	5	6	7	8
A		0	0	0	0	0	0	0	0	0					
				350				374							
					40		40								
B		0	0	0	0	0	0	0	0	0					
							49								
C		0	0	70	0	0	0	0	0	0					
					393										
					60										
D		0	0	0	0	0	0	0	0	0					
									366	378					
E	0	0	0	0	0	0	0	0	0	0					
					375			358							
					64										
F	0	0	0	0	0	0	0	0	0	0					
		357						375	374						
		65	46		59										
G	0	0	0	0	0	0	0	0	0	0					
	357		375		352			385							
	35	32					41								
H	0	0	0	0	0	0	0	0	0	0					
	378									360					
					36	42									
I		0	0	0	0	0	0	0	0	0					
					385				389						
			38												
J		0	0	0	0	0	0	0	0	0					
									363						
					45		46								
K		0	0	50	0	0	0	0	0	0					
				378				365							

Invert

Crown
East

Invert

Key	
Pit Depth Measurements (mils)	
Ultrasonic Thickness (mils)	
Coating Thickness (mils)	
Buried Pipe	

Deepest Pit: 70
 Lowest UT: 352
 Design Thickness : 0.375-in

Location: Sta. 229+85
 Date: 17-Mar-23

APPENDIX II
Coating Thickness Log

Site #1

Created	2023-03-21 12:44:30
Gage S/N	889755
Probe Type	F
Probe S/N	381458
Gage Type	PosiTector

Calibration

Cal Name	Cal 1
Adjustment Date	20-30-02-03 20:56:46
Adjustment Method	Zero Offset: 0.65 mils

Summary


	#	✕	⊞	⬇	⬆
Thickness(mils)	58	38.077	20.233	1.25	70.90

Readings

#	Thickness (mils)	Time
1	31.6	2023-03-21 12:44:39
2	19.9	12:44:41
3	31.7	12:44:42
4	37.1	12:44:45
5	26.9	12:44:46
6	32.0	12:44:48
7	27.4	12:44:51
8	23.8	12:44:52
9	25.5	12:44:53
10	29.5	12:45:03
11	32.5	12:45:05
12	35.8	12:45:06
13	24.0	12:45:22
14	28.8	12:45:24
15	43.2	12:45:27
16	27.6	12:45:31
17	65.9	12:45:35
18	68.0	12:45:37
19	63.5	12:45:38
20	33.4	12:45:41
21	9.2	12:46:00
22	2.1	12:46:01
23	22.2	12:46:03
24	6.0	12:46:04

25	2.3	12:46:06
26	68.4	12:46:10
27	66.0	12:46:12
28	59.1	12:46:14
29	55.3	12:46:16
30	61.2	12:46:18
31	1.25	12:46:20
32	6.3	12:46:22
33	49.9	12:46:28
34	58.2	12:46:30
35	51.7	12:46:31
36	49.9	12:46:32
37	47.9	12:46:34
38	7.4	12:46:36
39	45.9	12:46:43
40	29.4	12:46:44
41	26.6	12:46:46
42	32.3	12:46:47
43	25.2	12:46:52
44	32.7	12:46:54
45	24.2	12:46:57
46	27.2	12:47:02
47	22.9	12:47:09
48	58.7	13:04:07
49	64.8	13:04:10
50	64.3	13:04:12
51	70.9	13:04:14
52	50.5	13:04:16
53	59.1	13:04:18
54	56.1	13:04:22
55	62.9	13:04:23
56	65.6	13:04:25
57	5.4	13:04:27
58	51.3	13:04:31

B45



[Home](#)

Site 2



Coating Thickness Inspection Report



Created: 2023-02-13 11:31:29
PosiTector Body S/N: 889755
Probe Type: PosiTector 6000 F
Probe S/N: 381458

Summary

	#	\bar{x}	σ	\downarrow	\uparrow
Coating Thickness (mils)	112	15.365	10.300	0.25	41.3



Readings

#	Thickness (mils)	Time
2023-03-16		
1	18.1	09:07:24
2	35.5	09:07:27
3	34.9	09:07:28
4	35.8	09:07:30
5	30.5	09:07:32
6	41.3	09:07:34
7	29.1	09:07:36
8	15.6	09:07:54
9	13.1	09:07:56
10	15.2	09:07:58
11	2.9	09:08:00
12	4.1	09:08:02
13	4.4	09:08:03
14	32.7	09:08:21
15	29.9	09:08:22
16	33.1	09:08:23

Readings

#	Thickness (mils)	Time
2023-03-16		
17	14.6	09:08:26
18	23.5	09:08:28
19	29.9	09:08:29
20	19.7	09:08:36
21	24.7	09:08:37
22	24.9	09:08:39
23	28.5	09:08:42
24	31.0	09:08:43
25	30.1	09:08:44
26	14.5	09:08:46
27	27.9	09:08:47
28	17.5	09:08:48
29	23.4	09:08:51
30	24.3	09:08:53
31	22.9	09:08:53
32	23.4	09:08:55
33	7.0	09:09:03
34	21.5	09:32:57
35	13.1	09:32:58
36	27.7	09:33:00
37	31.4	09:33:02
38	27.0	09:33:03
39	10.0	09:33:06
40	13.8	09:33:07
41	16.0	09:33:08
42	16.3	09:33:10
43	4.7	09:33:12
44	8.0	09:33:13
45	19.0	09:38:22
46	21.3	09:38:24
47	15.9	09:38:26
48	25.4	09:38:28
49	6.9	09:38:32
50	26.8	09:38:34
51	7.0	09:38:36
52	6.4	09:38:37
53	6.5	09:38:40
54	12.2	09:38:42
55	19.8	09:38:44
56	8.3	10:25:29
57	7.5	10:25:30
58	2.1	10:25:31
59	2.6	10:25:32
60	13.8	10:25:34
61	9.6	10:25:35
62	3.8	10:25:37
63	0.25	10:25:38
64	1.35	10:25:39
65	1.50	10:25:40
66	2.1	10:25:42
67	2.9	10:25:43

Site 2

Coating Thickness Inspection Report

Readings

#	Thickness (mils)	Time
		2023-03-16
68	3.2	10:25:44
69	6.5	10:25:45
70	17.5	10:25:46
71	15.8	10:25:47
72	11.4	10:25:48
73	6.6	10:25:50
74	12.9	10:25:51
75	19.7	10:25:55
76	5.4	10:25:56
77	4.1	10:25:57
78	2.0	10:26:26
79	1.65	10:26:27
80	2.1	10:26:28
81	5.7	10:26:30
82	3.0	10:26:31
83	5.7	10:26:32
84	3.1	10:26:33
85	10.2	10:26:34
86	4.7	10:26:35
87	6.1	10:26:38
88	2.4	10:26:38
89	4.6	10:27:00
90	3.9	10:27:01
91	3.3	10:27:02
92	22.7	10:27:07
93	15.3	10:27:08
94	12.5	10:27:09
95	9.5	10:27:12
96	11.7	10:27:13
97	12.8	10:27:14
98	12.2	10:27:16
99	21.7	10:27:17
100	10.0	10:27:18
101	7.2	10:27:24
102	10.9	10:27:25
103	12.0	10:27:26
104	20.2	10:27:28
105	28.3	10:27:29
106	32.0	10:27:30
107	21.7	10:27:34
108	21.2	10:27:35
109	20.7	10:27:36
110	25.1	10:27:39
111	24.8	10:27:40
112	30.3	10:27:40

Site #3

Created	2023-03-21 09:13:40
Gage S/N	889755
Probe Type	F
Probe S/N	381458
Gage Type	PosiTector

Calibration

Cal Name	Cal 1
Adjustment Date	20-30-02-03 20:56:46
Adjustment Method	Zero Offset: 0.65 mils

Summary


	#	✕	⊗	⬇	⬆
Thickness(mils)	55	29.99	11.16	4.6	54.9

Readings

#	Thickness (mils)	Time
1	17.1	2023-03-21 09:13:46
2	27.7	09:13:47
3	28.9	09:13:49
4	22.6	09:13:51
5	19.9	09:13:53
6	17.5	09:13:54
7	36.8	09:14:35
8	36.6	09:14:36
9	35.1	09:14:38
10	32.8	09:14:57
11	31.8	09:14:58
12	27.8	09:14:59
13	22.6	09:15:12
14	18.4	09:15:13
15	19.7	09:15:14
16	34.5	09:15:44
17	40.7	09:15:46
18	49.4	09:15:47
19	30.0	09:16:15
20	30.0	09:16:16
21	8.9	09:54:33
22	35.4	09:54:35
23	20.5	09:54:38
24	33.6	09:54:39

25	48.5	09:55:03
26	46.2	09:55:05
27	39.7	09:55:07
28	25.9	09:55:10
29	10.2	09:55:22
30	22.8	09:55:24
31	38.3	09:55:26
32	31.4	09:55:29
33	44.6	09:55:40
34	33.7	09:55:42
35	31.5	09:55:44
36	30.8	09:55:47
37	24.5	09:55:55
38	17.8	09:55:56
39	28.2	09:55:58
40	31.3	09:56:10
41	41.8	09:56:12
42	17.3	09:56:14
43	11.8	09:56:17
44	39.7	09:56:19
45	4.6	09:56:26
46	19.9	09:56:28
47	43.8	09:56:30
48	27.2	09:56:32
49	40.9	09:56:35
50	29.9	09:57:09
51	27.8	09:57:11
52	16.0	09:57:12
53	54.9	09:57:31
54	41.4	09:57:33
55	48.5	09:57:35

B44



[Home](#)

Site 4



Coating Thickness Inspection Report



Created: 2023-03-16 11:50:14
PosiTector Body S/N: 889755
Probe Type: PosiTector 6000 F
Probe S/N: 381458

Summary

	#	\bar{x}	σ	\downarrow	\uparrow
Coating Thickness (mils)	52	34.34	5.93	26.4	51.7



Readings

#	Thickness (mils)	Time
2023-03-16		
1	28.0	11:50:18
2	28.9	11:50:19
3	29.6	11:50:20
4	41.4	11:50:22
5	26.9	11:50:26
6	26.8	11:50:27
7	30.2	11:50:28
8	30.0	11:50:29
9	33.0	11:50:32
10	33.6	11:50:33
11	32.9	11:50:34
12	38.6	11:50:36
13	33.7	11:50:36
14	34.7	11:50:37
15	27.7	11:50:39
16	28.8	11:50:39

Readings

#	Thickness (mils)	Time
2023-03-16		
17	27.4	11:50:40
18	41.5	11:50:42
19	40.2	11:50:43
20	40.0	11:50:44
21	34.6	11:50:47
22	34.2	11:50:48
23	37.1	11:50:48
24	37.3	11:51:31
25	39.6	11:51:32
26	34.8	11:51:33
27	41.9	11:51:35
28	40.0	11:51:36
29	39.5	11:51:37
30	29.4	11:51:39
31	29.5	11:51:40
32	29.7	11:51:41
33	32.8	11:58:00
34	30.4	11:58:05
35	32.3	11:58:10
36	28.3	11:58:15
37	30.5	11:58:25
38	40.5	11:58:28
39	29.2	11:58:36
40	41.6	11:58:40
41	35.3	11:58:55
42	28.4	11:59:02
43	30.9	11:59:12
44	29.1	11:59:18
45	36.3	11:59:23
46	26.4	11:59:28
47	32.7	11:59:35
48	32.3	11:59:41
49	45.9	11:59:46
50	51.7	11:59:48
51	41.3	11:59:54
52	48.1	12:00:02

Site 5


Coating Thickness Inspection Report



Created: 2023-03-17 09:04:03
PosiTector Body S/N: 889755
Probe Type: PosiTector 6000 F
Probe S/N: 381458

Summary

	#	\bar{x}	σ	\downarrow	\uparrow
Coating Thickness (mils)	42	47.33	12.30	27.0	79.0



Readings

#	Thickness (mils)	Time
2023-03-17		
1	50.6	09:04:07
2	56.5	09:04:09
3	52.1	09:04:11
4	61.7	09:04:15
5	49.2	09:04:17
6	79.0	09:04:23
7	59.2	09:04:26
8	42.7	09:04:31
9	43.7	09:04:33
10	44.8	09:04:35
11	57.3	09:04:40
12	64.8	09:04:42
13	59.8	09:04:43
14	49.2	09:05:04
15	64.1	09:05:25
16	64.1	09:05:28

Readings

#	Thickness (mils)	Time
2023-03-17		
17	51.8	09:05:37
18	59.0	09:05:47
19	41.1	09:05:58
20	36.6	09:06:01
21	52.0	09:06:21
22	42.0	09:06:23
23	47.6	09:06:36
24	44.7	09:06:42
25	31.9	09:06:53
26	45.1	09:06:55
27	45.8	09:07:05
28	33.2	09:07:17
29	41.3	09:07:22
30	37.8	09:07:25
31	46.0	09:08:01
32	61.0	09:08:34
33	65.4	09:08:37
34	30.2	09:18:39
35	40.9	09:18:42
36	32.6	09:18:44
37	51.7	09:19:04
38	35.2	09:19:06
39	34.9	09:19:54
40	27.0	09:19:58
41	27.1	09:20:00
42	27.0	09:20:02

APPENDIX III
Soil Resistivity Measurements

	Test Site #1		3/21/2023
West	Soil Resistance (Ohm-cm)		East
Crown	9,000	4,500	Crown
Springline	10,000	12,000	Springline
Invert		5,000	Invert

	Test Site #2		3/16/2023
West	Soil Resistance (Ohm-cm)		East
Crown		10,000	Crown
Springline		1,500	Springline
Invert	1,000		Invert

	Test Site #3		3/21/2023
West	Soil Resistance (Ohm-cm)		East
Crown	17,000	50,000	Crown
Springline		12,000	Springline
Invert	2,500	2,000	Invert

	Test Site #4		3/16/2023
West	Soil Resistance (Ohm-cm)		East
Crown	8,000	3,000	Crown
Springline	3,500	1,000	Springline
Invert	2,000	1,500	Invert

	Test Site #6		3/17/2023
West	Soil Resistance (Ohm-cm)		East
Crown	60,000	100,000	Crown
Springline	60,000	100,000	Springline
Invert	25,000	75,000	Invert

APPENDIX IV
Photo Log



1 – Site 1 overview Sta 205+28



2 – Site 1 Crown



3 – Site 1 Springline and lock bar



4 – Deepest Pitting in Pipe at Site 1



5 – Site 1 Invert



6 – Site 1 Spring line and lock bar



7 – Site 2 overview Sta 214+00



8 – Site 2 Crown



9 – B-scan along Crown



10 – Springline and lock bar



11 – Deepest pit in Springline



12 – Site 2 Invert



13 – Site 3 overview Sta 217+17



14 – Site 3 crown and shoring



15 – Site 3 Springline and lock bar



16 – Typical condition of Springline



17 – Deepest pit in site 3



18 – Site 3 Invert



19 – Site 4 overview Sta 220+85



20 – Site 4 Crown



21 – Site 3 Springline and lock bar



22 – Typical coating condition



23 – Pitting in Springline



24 – Deepest pitting in Invert



25 – Site 5 overview Sta 229+85



26 – Site 5 Crown



27 – Site 5 Springline and lock bar



28 – Gashes in Springline coating



29 – Deepest pit in Springline of Site 5



30 – Site 5 Invert

Site 3 (2021 designation) 227+50

Site #3: Waverly Oaks Road: General Overview



Site #3: Waverly Oaks Road: Notable Pit



Site #3: Waverly Oaks Road: Notable Pit



Site #3: Waverly Oaks Road: Notable Pit




Site #3: Waverly Oaks Road: Coating De-lamination




APPENDIX V

Pipe Test Pit As-built Drawings Waverly Oaks Road


FILE NAME: \\US0552-PPSS01\Workgroup\1951\active\19510185\CAD\2.1.2 Field Testing Program\Excavation Locations\WMS3 Excavation - Location Plans_CP2_Phase2 - asbuilt.dwg LAYOUT NAME: C-110 PLOTTED: Thursday, April 13, 2023 - 12:53pm USER: toasmo



PLAN
SCALE: HORIZ 1"=40'



PROFILE
SCALE: HORIZ 1"=40'
VERT 1"=4'



NO.	DATE	BY	CHK'D	REVISION

CONTRACT NO. :	6539	CAD FILE NO. :	--
ACCESSION NO. :	----	SECTION NO. :	--
DATE:	DECEMBER 2022	DESIGNED BY:	TJC
SCALE:	AS NOTED	DRAWN BY:	TJC
		CHECKED BY:	RJS
		APPROVED BY:	----



MASSACHUSETTS WATER RESOURCES AUTHORITY

PREPARED BY :



45 NETWORK DRIVE 3RD FLOOR
BURLINGTON, MA 01803
www.stantec.com


WESTON AQUEDUCT SUPPLY MAIN 3
MWRA CONTRACT NO. 6539
CP2 PHASE 2 EXCAVATION LOCATIONS

EXCAVATION SITE 1 PLAN
173 LINDEN STREET - WALTHAM, MA


DRAWING NO.

1 OF 3


FILE NAME: \\US0552-PPSS01\Workgroup\1951\active\195150185\CAD\2.1.2.2 Field Testing Program\Excavation Locations\WASM3 Excavation - Location Plans_CP2_Phase2 - asbuilt.dwg LAYOUT NAME: C-111 PLOTTED: Thursday, April 13, 2023 - 12:54pm USER: toasmo



PLAN
SCALE: HORIZ 1"=40'



PROFILE
SCALE: HORIZ 1"=40'
VERT 1"=4'



NO.	DATE	BY	CHK'D	REVISION

CONTRACT NO. : 6539	WASM3 Excavation - Location Plans_CP2_Phase2 - asbuilt
ACCESSION NO. : ----	SECTION NO. : --
DATE: DECEMBER 2022	DESIGNED BY: RJS
SCALE: AS NOTED	DRAWN BY: TJC
	CHECKED BY: RBS
	APPROVED BY: ----



MASSACHUSETTS WATER RESOURCES AUTHORITY

PREPARED BY :




45 NETWORK DRIVE 3RD FLOOR
BURLINGTON, MA 01803
www.stantec.com

WESTON AQUEDUCT SUPPLY MAIN 3
MWRA CONTRACT NO. 6539
CP2 PHASE 2 EXCAVATION LOCATIONS

EXCAVATION SITES 2 & 3 PLAN
56 WAVERLEY OAKS ROAD - WALTHAM, MA

DRAWING NO.

2 OF 3



1" = 40'-0" HORIZONTAL
0 40 100 200
0 4 8 10 20
1" = 4'-0" VERTICAL

CONTRACT NO. : 6539 WASM3		EXPLANATION - Location Plans_CP2_Phase2 - asbuilt	
ACCESSION NO. : ----		SECTION NO. : --	
DATE: DECEMBER 2022		DESIGNED BY: RJG	
		DRAWN BY: TJC	
		CHECKED BY: NBS	
SCALE: AS NOTED		APPROVED BY: ----	



EXCAVATION SITES 3 & 4 PLAN
191 WAVERLEY OAKS ROAD - WALTHAM, MA