



21 Griffin Rd. North
Windsor, CT 06095

T 860.298.9692
TRCcompanies.com

May 1, 2025

Mr. Jason Coite P.E.
Principal Engineer
Division of Environmental Compliance
Bureau of Engineering and Construction
State of Connecticut Department of Transportation
2800 Berlin Turnpike, P.O. Box 317546
Newington, CT 06131-7546

Attention: D. Imig, P.E. / B. Silverman

Subject: On-Call Asbestos, Lead, Air Quality & Demolition Compliance
Agreement No. 10.04-02 (23)
HazMat Inspection – Replacement of Bridge No. 03474, Route 200 over Interstate 395,
Thompson, CT
ConnDOT Assignment No. 524-8423
ConnDOT Project No. 141-158
TRC Project No. 501871.8423.0710

Dear Mr. Coite:

TRC performed a limited hazardous materials site investigation associated with the replacement of Bridge No. 03474, Route 200 over Interstate 395, Thompson, CT. Results of the survey identified lead paint on the metal railings/railing support components (on both sides) and the structural steel/metal bridge components (on underside) at Bridge No. 03474. Results obtained from TCLP waste stream sampling and analysis for leachable lead from the paint on the railings/railing support components and structural steel/ metal bridge components characterized the paint waste streams at Bridge No. 03474 as **CTDEEP/RCRA hazardous waste**. All suspect asbestos-containing materials (various caulks, black asphaltic plug joint, black tar joint/curb filler, and tan bearing rope gasket) identified and sampled at Bridge No. 03474 were determined to be non-asbestos containing materials. No bird/pigeon guano, mice droppings/nests, bloodborne pathogens (BBP) concerns, homeless activity, or other hazmat/regulated items were identified at Bridge No. 03474.

Laboratory results, XRF Measurement Data Summary Table, and TRC Mobile Data Solutions report are attached.

If you have any questions, please call TRC at (860) 298-9692.

Very Truly Yours,

TRC

Stephen R. Arienti, CHMM
New England Regional Practice Leader – Engineer in Charge

Erik R. Plimpton, P.E., CHMM, CMC
Vice President – Engineer in Charge



BULK ASBESTOS ANALYSIS REPORT

CLIENT: CT Department of Transportation

Lab Log #: 0066628
 Project #: 501871.8423.0710
 Date Received: 03/05/2025
 Date Analyzed: 03/07/2025

Site: Bridge 03474, Thompson Hill Road over Route 395, Thompson, CT

POLARIZED LIGHT MICROSCOPY by EPA 600/R-93/116

Sample No.	Sample Location	Homogeneous Material Description	Other Matrix Materials	Asbestos %	Asbestos Type	
1	South side railing	White C1 - caulk on south side bridge railings	---	ND	None	
2	South side railing	White C1 - caulk on south side bridge railings	---	ND	None	
3	South side	Grey C2 - caulk in bridge joints	---	ND	None	
4	North side	Grey C2 - caulk in bridge joints	---	ND	None	
5	South side	Grey C3 - caulk in bridge seams	---	ND	None	
6	North side	Grey C3 - caulk in bridge seams	---	ND	None	
7	North railing	Black C4 - caulk around north side railings	---	ND	None	
8	North railing	Black C4 - caulk around north side railings	---	ND	None	
9	Black road tar	Black RT 1 - road tar	---	ND	None	
10	Black road tar	Black RT 1 - road tar	---	ND	None	
11	South side	Black TJF 1 - tar joint filler in joints and along curb	---	ND	None	
12	North side	Black TJF 1 - tar joint filler in joints and along curb	---	ND	None	
13	Bearing under bridge	Tan RG 1 - rope gasket around bearing bases	99%	cellulose	ND	None
14	Bearing under bridge	Tan RG 1 - rope gasket around bearing bases	99%	cellulose	ND	None

TRC LABORATORY ASBESTOS ANALYTICAL ACCREDITATIONS

NVLAP Lab Code 101424-0
 RI #PLM00007 TX #300354
 CO# AL-21772

AIHA LAP #100122
 VT #An-000020
 LA#05011

CT #PH-0426
 VA #3333 000283
 PA#68-03387

ME LB-0071
 AZ #AZ0944
 PHIL#ALL-461

MA #AA000052
 HI #L-09-004

NY #10980
 NV #CT00004
 WV #000622
 CA #2907
 WA #C1071



POLARIZED LIGHT MICROSCOPY by EPA 600/R-93/116


Sample No.	Sample Location	Homogeneous Material Description	Other Matrix Materials	Asbestos %	Asbestos Type
------------	-----------------	----------------------------------	------------------------	------------	---------------


ND - asbestos was not detected
 Trace - asbestos was observed at level of 1% or less - This is the reporting limit
 NA/PS - Not Analyzed / Positive Stop
 SNA - Sample Not Analyzed- See Chain of Custody for details
 Notes: Asbestos-Containing Material (ACM) is any material containing more than 1% asbestos

Note: Polarized-light microscopy is not consistently reliable in detecting asbestos in floor coverings and similar non-friable organically bound materials. In those cases, EPA recommends, and certain states (e.g. NY) require, that negative results be confirmed by quantitative transmission electron microscopy.

The Laboratory at TRC follows 18/01A EPA -- 40 CFR Appendix E to subpart E of Part 763, Interim Method of the Determination of Asbestos in Bulk Insulation Samples and 18/A03 EPA 600/R-93/116: Method for the Determination of Asbestos in Bulk Building Materials which utilize polarized light microscopy (PLM). Our analysts have completed an accredited course in asbestos identification. TRC's Laboratory is accredited under the National Voluntary Laboratory Accreditation Program (NVLAP), for Bulk Asbestos Fiber Analysis, NVLAP Code 101424-01. TRC is accredited by the AIHA Laboratory Accreditation Programs AIHA LAP (ID: LAP-100122) in the Industrial Hygiene Program (IHLAP) for PLM. Asbestos content is determined by visual estimate unless otherwise indicated. Quality Control is performed in-house on at least 10% of samples and QC data related to the samples is available upon written request from client.

This report shall not be reproduced, except in full, without the written approval of TRC. This report must not be used by the client to claim product endorsement by NVLAP or any agency of the U.S. Government. This report relates only to the items tested, as received by the laboratory.

Analyzed by: 
 Drue Marino, Laboratory Analyst

Reviewed by 
 Kathleen Williamson, Laboratory Manager

Date Issued
 03/07/2025

TRC LABORATORY ASBESTOS ANALYTICAL ACCREDITATIONS

NVLAP Lab Code 101424-0	AIHA LAP #100122	CT #PH-0426	ME LB-0071	MA #AA000052	NY #10980	WV #000622
RI #PLM00007 TX #300354	VT #An-000020	VA #3333 000283	AZ #AZ0944	HI #L-09-004	NV #CT00004	CA #2907
CO# AL-21772	LA#05011	PA#68-03387	PHIL#ALL-461		WA #C1071	



21 GRIFFIN ROAD NORTH
 WINDSOR, CONNECTICUT 06095
 TELEPHONE (860) 298-9692
 FAX (860) 298-6380

ASBESTOS BULK SAMPLING CHAIN OF CUSTODY

Edition: October 2009
 Supersede Previous Edition

LAB ID #. *66628*

PROJECT NUMBER 501871.8423.0710			PROJECT NAME ConnDOT — Bridge No.03474, Thompson hill Rd Over Route 395			PARAMETERS					TURNAROUND TIME					
											PLM:	8hr	24hr	48hr	X	3day
SIGNATURE 			INSPECTOR Alex Lemay, Andrew Smith			PLM EPA 600/R93/I16 (POSITIVE STOP)	PLM EPA 600/R93/I16 (w/ gravimetric reduction) (POSITIVE STOP)	ANALYZE BY LAYER	POINT COUNT (IF >1% & <10%)	TEM NY NOB 198.4 (IF PLM SERIES NEG)	MATERIAL					
											TEM:	24hr	48hr	3day	X	5day
FIELD SAMPLE NUMBER	DATE	TIME	COMP	GRAB	SAMPLE LOCATION											
1	3/5/2025	10:53		X	South side railing	X				X	C1 - White caulk on south side bridge railings					
2	3/5/2025	10:53		X	South side railing	X					C1 - White caulk on south side bridge railings					
3	3/5/2025	11:08		X	South side	X				X	C2 - Grey caulk in bridge joints					
4	3/5/2025	11:08		X	North side	X					C2 - Grey caulk in bridge joints					
5	3/5/2025	11:03		X	South side	X				X	C3 - Grey caulk in bridge seams					
6	3/5/2025	11:03		X	North side	X					C3 - Grey caulk in bridge seams					
7	3/5/2025	11:18		X	North railing	X				X	C4 - Black caulk around north side railings					
8	3/5/2025	11:18		X	North railing	X					C4 - Black caulk around north side railings					
9	3/5/2025	11:14		X	Black road tar	X				X	RT 1 - Black road tar					
10	3/5/2025	11:14		X	Black road tar	X					RT 1 - Black road tar					
11	3/5/2025	11:10		X	South side	X				X	TJF 1 - Black Tar joint filler In joints and along curb					
12	3/5/2025	11:11		X	North side	X					TJF 1 - Black Tar joint filler In joints and along curb					

Relinquished by: (Signature) 	Date: <i>3/5/25</i>	Received by: (Signature) <i>Najaast Bhura</i>	Date: <i>3/5/25</i>	Received by: (Signature) <i>Najaast Bhura</i>
(Printed) <i>Andrew Smith</i>	Time: <i>15:10</i>	(Printed) <i>Najaast Bhura</i>	Time:	(Printed)
Remarks:			Condition of Samples: Acceptable: Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Comments:	



21 GRIFFIN ROAD NORTH
 WINDSOR, CONNECTICUT 06095
 TELEPHONE (860) 298-9692
 FAX (860) 298-6380

ASBESTOS BULK SAMPLING CHAIN OF CUSTODY

Edition: October 2009
 Supersede Previous Edition

LAB ID #. 66628

PROJECT NUMBER 501871.8423.0710			PROJECT NAME ConnDOT — Bridge No.03474, Thompson hill Rd Over Route 395			PARAMETERS			TURNAROUND TIME							
									PLM:		8hr		24hr		48hr	X
SIGNATURE 			INSPECTOR Alex Lemay, Andrew Smith													
									TEM:		24hr		48hr		3day	X
FIELD SAMPLE NUMBER	DATE	TIME	TYPE		SAMPLE LOCATION	PLM EPA 600/R93/I16 (POSITIVE STOP)	PLM EPA 600/R93/I16 (w/ gravimetric reduction) (POSITIVE STOP)	ANALYZE BY LAYER	POINT COUNT (IF >1% & <10%)	TEM NY NOB 198.4 (IF PLM SERIES NEG)	MATERIAL					
			COMP	GRAB												
13	3/5/2025	11:38		X	Bearing under bridge	X					RG 1 - Tan rope gasket around bearing bases					
14	3/5/2025	11:38		X	Bearing under bridge	X					RG 1 - Tan rope gasket around bearing bases					

Relinquished by: (Signature) 	Date: 3/5/2025	Received by: (Signature) <u>315125</u> 	Relinquished by: (Signature)	Date:	Received by: (Signature)
(Printed) Andrew Smith	Time: 15:00	(Printed) Najaat Bhura	(Printed)	Time:	(Printed)
Remarks:			Condition of Samples: Acceptable: Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>		Page 2 of 2



EMSL Analytical, Inc.

528 Mineola Avenue Carle Place, NY 11514

Tel/Fax: (516) 997-7251 / (516) 997-7528

<http://www.EMSL.com> / carleplacelab@emsl.com

EMSL Order: 062502990

Customer ID: TRC51

Customer PO: C501871

Project ID:

Attention: Kathleen Williamson
TRC Environmental Consultants
21 Griffin Road North
Windsor, CT 06095

Phone: (860) 298-9692
Fax: (860) 298-6399
Received Date: 03/11/2025 10:49 AM
Analysis Date: 03/14/2025
Collected Date: 03/05/2025

Project: C501971, 501871.8423.0710, CT DOT- Bridge 03474, Thomposon Hill Road over Route 395, Thompson, CT

Test Report: Asbestos Analysis of Non-Friable Organically Bound Materials by TEM via EPA/600/R-93/116 Section 2.5.5.1

Sample ID	Description	Appearance	% Matrix Material	% Non-Asbestos Fibers	Asbestos Types
1 062502990-0001	South side railing - C1- White caulk on south side of bridge railings	White/Beige Non-Fibrous Heterogeneous	100.0 Other	None	No Asbestos Detected
3 062502990-0002	South side - C2- Grey caulk in bridge joints	Brown/Gray Non-Fibrous Heterogeneous	100.0 Other	None	No Asbestos Detected
5 062502990-0003	South side - C3- Grey caulk in bridge seams	Gray/White Non-Fibrous Heterogeneous	100.0 Other	None	No Asbestos Detected
7 062502990-0004	North railing - C4- Black caulk around north side railings	Brown/Black Non-Fibrous Heterogeneous	100.0 Other	None	No Asbestos Detected
9 062502990-0005	Black road tar - RT1- Black road tar	Brown/Black Non-Fibrous Heterogeneous	100.0 Other	None	No Asbestos Detected
11 062502990-0006	South side - TJF 1- Black Tar joint filler in joint and along curb	Brown/Black Non-Fibrous Heterogeneous	100.0 Other	None	No Asbestos Detected

Analyst(s)

Taylor Power (6)

Daniel Clarke, Asbestos Laboratory Manager
or other approved signatory

EMSL maintains liability limited to cost of analysis. Interpretation and use of test results are the responsibility of the client. This report relates only to the samples reported above, and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. The report reflects the samples as received. Results are generated from the field sampling data (sampling volumes and areas, locations, etc.) provided by the client on the Chain of Custody. Samples are within quality control criteria and met method specifications unless otherwise noted. EMSL recommends that samples reported as none detected or <1% undergo additional analysis via PLM to avoid the possibility of false negatives.

Samples analyzed by EMSL Analytical, Inc. Carle Place, NY

Initial report from: 03/17/2025 08:38:17



Client: Mr. Stephen Arienti
TRC Environmental Consultants
21 Griffin Rd., North
Windsor, CT 06095

Analytical Report

CET# 25C0171

Report Date: March 12, 2025
Project: Bridge 03474, Thompson Hill Rd over 395
Project Number: 501871.8423-0710

Connecticut Laboratory Certificate: PH 0116
Massachusetts Laboratory Certificate: M-CT903
Rhode Island Laboratory Certificate: 199



New York NELAP Accreditation: 11982
Pennsylvania Laboratory Certificate: 68-02927

CET # : 25C0171

Project: Bridge 03474, Thompson Hill Rd over 395

Project Number: 501871.8423-0710

SAMPLE SUMMARY

The sample(s) were received at 22.0°C.

This report contains analytical data associated with following samples only.

Sample ID	Laboratory ID	Matrix	Collection Date/Time	Receipt Date
2	25C0171-02	Paint Chip	3/05/2025	03/06/2025

Analyte: TCLP Lead [EPA 6020B]

Analyst: EAS

Matrix: Extract

Laboratory ID	Client Sample ID	Result	RL	Units	Dilution	Batch	Prepared	Date/Time Analyzed	Notes
25C0171-02	2	540	0.26	mg/L	20	BC51122	03/11/2025	03/12/2025 13:29	

CET # : 25C0171

Project: Bridge 03474, Thompson Hill Rd over 395

Project Number: 501871.8423-0710

QUALITY CONTROL SECTION

Batch BC51122 - EPA 6020B

Analyte	Result (mg/L)	RL (mg/L)	Spike Level	Source Result	% Rec	% Rec Limits	RPD	RPD Limit	Notes
Blank (BC51122-BLK1)					Prepared: 3/11/2025 Analyzed: 3/11/2025				
Lead	ND	0.013							
LCS (BC51122-BS1)					Prepared: 3/11/2025 Analyzed: 3/11/2025				
Lead	0.193	0.013	0.200		96.7	80 - 120			
LCS Dup (BC51122-BSD1)					Prepared: 3/11/2025 Analyzed: 3/11/2025				
Lead	0.194	0.013	0.200		96.8	80 - 120	0.0647	20	



80 Lupes Drive
Stratford, CT 06615

Tel: (203) 377-9984
Fax: (203) 377-9952
email: cet1@cetlabs.com

Quality Control Definitions and Abbreviations

Internal Standard (IS)	An Analyte added to each sample or sample extract. An internal standard is used to monitor retention time, calculate relative response, and quantify analytes of interest.
Surrogate Recovery	The % recovery for non-target organic compounds that are spiked into all samples. Used to determine method performance.
Continuing Calibration Batch	An analytical standard analyzed with each set of samples to verify initial calibration of the system. Samples that are analyzed together with the same method, sequence and lot of reagents within the same time period.
ND	Not detected at or above the specified reporting limit.
RL	RL is the limit of detection for an analyte after any adjustment made for dilution or percent moisture.
Dilution	Multiplier added to detection levels (MDL) and/or sample results due to interferences and/or high concentration of target compounds.
Duplicate Result	Result from the duplicate analysis of a sample. Amount of analyte found in a sample.
Spike Level	Amount of analyte added to a sample
Matrix Spike Result	Amount of analyte found including amount that was spiked.
Matrix Spike Dup	Amount of analyte found in duplicate spikes including amount that was spike.
Matrix Spike % Recovery	% Recovery of spiked amount in sample.
Matrix Spike Dup % Recovery	% Recovery of spiked duplicate amount in sample.
RPD	Relative percent difference between Matrix Spike and Matrix Spike Duplicate.
Blank	Method Blank that has been taken through all steps of the analysis.
LCS % Recovery	Laboratory Control Sample percent recovery. The amount of analyte recovered from a fortified sample.
Recovery Limits	A range within which specified measurements results must fall to be compliant.
CC	Calibration Verification

Flags:

- H- Recovery is above the control limits
- L- Recovery is below the control limits
- B- Compound detected in the Blank
- P- RPD of dual column results exceeds 40%
- #- Sample result too high for accurate spike recovery.



Connecticut Laboratory Certification PH0116
Massachusetts Laboratory Certification M-CT903
Pennsylvania NELAP Accreditation 68-02927

New York NELAP Accreditation 11982
Rhode Island Certification 199

CET # : 25C0171


Project: Bridge 03474, Thompson Hill Rd over 395

Project Number: 501871.8423-0710

All questions related to this report should be directed to David Ditta, Timothy Fusco, or Jeffrey Smith at 203-377-9984.

Sincerely,

This technical report was reviewed by David Ditta



David Ditta
Laboratory Director

Project Manager

This report shall not be reproduced except in full, without the written approval of the laboratory

Report Comments:

Sample Result Flags:

- E- The result is estimated, above the calibration range.
- H- The surrogate recovery is above the control limits.
- L- The surrogate recovery is below the control limits.
- B- The compound was detected in the laboratory blank.
- P- The Relative Percent Difference (RPD) of dual column analyses exceeds 40%.
- D- The RPD between the sample and the sample duplicate is high. Sample Homogeneity may be a problem.
- + - The Surrogate was diluted out.
- *C1- The Continuing Calibration did not meet method specifications and was biased low for this analyte. Increased uncertainty is associated with the reported value which is likely to be biased low.
- *C2- The Continuing Calibration did not meet method specifications and was biased high for this analyte. Increased uncertainty is associated with the reported value which is likely to be biased high.
- *F1- The Laboratory Control Sample recovery is outside of control limits. Reported value for this analyte is likely to be biased on the low side.
- *F2- The Laboratory Control Sample recovery is outside of control limits. Reported value for this analyte is likely to be biased on the high side.
- *I- Analyte exceeds method limits from second source standard in Initial Calibration Verification (ICV). No directional bias.

All results met standard operating procedures unless indicated by a data qualifier next to a sample result, or a narration in the QC report.

For Percent Solids, if any of the following prep methods (3050B, 3540C, 3545A, 3550C, 5035 and 9013A) were used for samples pertaining to this report, the percent solids procedure is within that prep method.

Complete Environmental Testing is only responsible for the certified testing and is not directly responsible for the integrity of the sample before laboratory receipt.

ND is None Detected at or above the specified reporting limit

Reporting Limit (RL) is the limit of detection for an analyte after any adjustment made for dilution or percent moisture.

All analyses were performed in house unless a Reference Laboratory is listed.

Samples will be disposed of 30 days after the report date.

CET # : 25C0171

Project: Bridge 03474, Thompson Hill Rd over 395

Project Number: 501871.8423-0710

CERTIFICATIONS

Certified Analyses included in this Report

Analyte	Certifications
<i>EPA 6020B in Water</i>	
Lead	CT

Complete Environmental Testing operates under the following certifications and accreditations:

Code	Description	Number	Expires
CT	Connecticut Public Health	PH0116	09/30/2026



Client: Mr. Stephen Arienti
TRC Environmental Consultants
21 Griffin Rd., North
Windsor, CT 06095

Analytical Report

CET# 25C0218

Report Date: March 14, 2025
Project: Bridge No. 03474, Thompson
Project Number: 501871.8423.0710

Connecticut Laboratory Certificate: PH 0116
Massachusetts Laboratory Certificate: M-CT903
Rhode Island Laboratory Certificate: 199



New York NELAP Accreditation: 11982
Pennsylvania Certificate: 68-02927

CET # : 25C0218

Project: Bridge No. 03474, Thompson

Project Number: 501871.8423.0710

SAMPLE SUMMARY

The sample(s) were received at 22.0°C.

This report contains analytical data associated with following samples only.

Sample ID	Laboratory ID	Matrix	Collection Date/Time	Receipt Date
01	25C0218-01	Paint Chip	3/10/2025 13:00	03/11/2025

Analyte: TCLP Lead [EPA 6020B]

Analyst: EAS

Matrix: Extract

Laboratory ID	Client Sample ID	Result	RL	Units	Dilution	Batch	Prepared	Date/Time Analyzed	Notes
25C0218-01	01	11	0.13	mg/L	10	BC51334	03/13/2025	03/13/2025 17:52	

CET # : 25C0218


Project: Bridge No. 03474, Thompson

Project Number: 501871.8423.0710


All questions related to this report should be directed to David Ditta, Timothy Fusco, or Jeffrey Smith at 203-377-9984.

Sincerely,

This technical report was reviewed by Ashley Mestuzzi



David Ditta
Laboratory Director



Project Manager

This report shall not be reproduced except in full, without the written approval of the laboratory

Report Comments:

Sample Result Flags:

- E- The result is estimated, above the calibration range.
- H- The surrogate recovery is above the control limits.
- L- The surrogate recovery is below the control limits.
- B- The compound was detected in the laboratory blank.
- P- The Relative Percent Difference (RPD) of dual column analyses exceeds 40%.
- D- The RPD between the sample and the sample duplicate is high. Sample Homogeneity may be a problem.
- + - The Surrogate was diluted out.
- *C1- The Continuing Calibration did not meet method specifications and was biased low for this analyte. Increased uncertainty is associated with the reported value which is likely to be biased low.
- *C2- The Continuing Calibration did not meet method specifications and was biased high for this analyte. Increased uncertainty is associated with the reported value which is likely to be biased high.
- *F1- The Laboratory Control Sample recovery is outside of control limits. Reported value for this analyte is likely to be biased on the low side.
- *F2- The Laboratory Control Sample recovery is outside of control limits. Reported value for this analyte is likely to be biased on the high side.
- *I- Analyte exceeds method limits from second source standard in Initial Calibration Verification (ICV). No directional bias.

All results met standard operating procedures unless indicated by a data qualifier next to a sample result, or a narration in the QC report.

For Percent Solids, if any of the following prep methods (3050B, 3540C, 3545A, 3550C, 5035 and 9013A) were used for samples pertaining to this report, the percent solids procedure is within that prep method.

Complete Environmental Testing is only responsible for the certified testing and is not directly responsible for the integrity of the sample before laboratory receipt.

ND is None Detected at or above the specified reporting limit

Reporting Limit (RL) is the limit of detection for an analyte after any adjustment made for dilution or percent moisture.

All analyses were performed in house unless a Reference Laboratory is listed.

Samples will be disposed of 30 days after the report date.

CET # : 25C0218

Project: Bridge No. 03474, Thompson

Project Number: 501871.8423.0710

CERTIFICATIONS

Certified Analyses included in this Report

Analyte **Certifications**

EPA 6020B in Water

Lead CT

Complete Environmental Testing operates under the following certifications and accreditations:

Code	Description	Number	Expires
CT	Connecticut Public Health	PH0116	09/30/2026



Lead Based Paint Measurement Summary Table

Device(s) : Niton XLP301-A (Serial #24792) X Ray Fluorescence (XRF) Spectrum Analyzer
 Client : ConnDOT
 Site : Bridge No. 03474, Route 200 over Interstate 395, Thompson, CT
 Project # : 501871.8423.0710
 Date(s) : 3/5/2025
 Inspector : Alex Lemay

Number	Bridge	Location	Side	Structure	Feature	Material	Color	Condition	Reading (mg/cm ²)	Precision (mg/cm ²)	Depth Index	Duration (sec)	Date/Time
1		Shutter Calibration							3.0	0.0		118.34	3/5/2025 11:26
2		Calibration 0.0							0.0	0.02	1.0	3.45	3/5/2025 11:42
3		Calibration 3.6							3.7	0.3	1.3	5.16	3/5/2025 11:42
4		Calibration 0.7							0.7	0.1	1.07	6.38	3/5/2025 11:43
5	Bridge 03474	Top Of Bridge		Railing	Rail	Metal	Grey	Defective	0.2	0.81	2.62	0.25	3/5/2025 11:45
6	Bridge 03474	Top Of Bridge	South	Railing	Rail	Metal	Grey	Defective	0.1	0.06	2.72	8.57	3/5/2025 11:46
7	Bridge 03474	Top Of Bridge	South	Railing	Rail	Metal	Grey	Defective	0.1	0.03	1.88	8.34	3/5/2025 11:47
8	Bridge 03474	Top Of Bridge	South	Railing	Rail	Metal	Grey	Defective	0.1	0.05	2.24	6.38	3/5/2025 11:47
9	Bridge 03474	Top Of Bridge	South	Railing	Post	Metal	Grey	Defective	0.3	0.1	2.89	7.65	3/5/2025 11:48
10	Bridge 03474	Top Of Bridge	South	Railing	Post	Metal	Grey	Defective	0.3	0.13	3.19	6.15	3/5/2025 11:49
11	Bridge 03474	Top Of Bridge	South	Railing	Base	Metal	Grey	Defective	0.1	0.07	2.99	7.14	3/5/2025 11:50
12	Bridge 03474	Top Of Bridge	South	Railing	Rail	Metal	Orange	Defective	0.0	0.91	10.0	10.29	3/5/2025 11:52
13	Bridge 03474	Top Of Bridge	South	Railing	Rail	Metal	Orange	Defective	0.2	0.24	10.0	11.54	3/5/2025 11:52
14	Bridge 03474	Top Of Bridge	South	Railing	Rail	Metal	Orange	Defective	0.2	0.11	3.98	5.4	3/5/2025 11:53
15	Bridge 03474	Top Of Bridge	North	Railing	Rail	Metal	Grey	Defective	0.2	0.07	1.99	5.66	3/5/2025 11:56
16	Bridge 03474	Top Of Bridge	North	Railing	Rail Segment Joint	Metal	Grey	Defective	0.1	0.07	2.13	5.18	3/5/2025 11:57
17	Bridge 03474	Top Of Bridge	North	Railing	Base	Metal	Grey	Defective	0.2	0.09	3.98	6.15	3/5/2025 11:58
18	Bridge 03474	Top Of Bridge	North	Railing	Post	Metal	Grey	Defective	0.2	0.08	2.22	6.67	3/5/2025 11:58
19	Bridge 03474	Top Of Bridge	North	Railing	Base Bearing	Metal	Grey	Defective	0.1	0.07	3.73	4.92	3/5/2025 11:59
20	Bridge 03474	Top Of Bridge	South	Railing	Rail Segment Joint	Metal	Grey	Defective	10.1	16.0	2.76	0.24	3/5/2025 12:14
21	Bridge 03474	Top Of Bridge	South	Railing	Rail Segment Joint	Metal	Grey	Defective	13.7	2.7	2.47	4.41	3/5/2025 12:14
22	Bridge 03474	Under Bridge		Support Beam		Metal	Grey	Defective	0.0	0.02	1.47	4.9	3/5/2025 12:33
23	Bridge 03474	Under Bridge		Support Beam		Metal	Grey	Defective	0.2	0.15	6.55	5.17	3/5/2025 12:33
24	Bridge 03474	Under Bridge		Support Beam		Metal	Grey	Defective	0.0	0.04	1.74	1.48	3/5/2025 12:34
25	Bridge 03474	Under Bridge		Support Beam		Metal	Grey	Defective	0.1	0.23	4.7	1.72	3/5/2025 12:34
26	Bridge 03474	Under Bridge		Support Beam		Metal	Grey	Defective	26.1	3.7	5.25	4.16	3/5/2025 12:34
27	Bridge 03474	Under Bridge	South	Railing	Rail	Metal	Grey	Defective	0.1	0.24	8.56	4.17	3/5/2025 12:37
28	Bridge 03474	Under Bridge	South	Railing	Rail	Metal	Grey	Defective	0.1	0.05	1.89	4.4	3/5/2025 12:38
29		Calibration 0.0							0.0	0.02	1.0	5.17	3/5/2025 13:10
30		Calibration 3.6							3.6	0.3	1.26	4.92	3/5/2025 13:10
31		Calibration 0.7							0.7	0.1	1.06	6.38	3/5/2025 13:10

SIH - WinSIH HBM Survey

ConnDOT, Bridge No.03474, Thompson hill Rd Over Route 395

3/10/2025, 7:55:58 PM UTC

CREATED

🕒 3/5/2025, 3:45:32 PM UTC

👤 by Andrew Smith

UPDATED

🕒 3/10/2025, 7:55:58 PM UTC

👤 by Cole Bova

STATUS

🟠 Complete

ASSIGNED TO

👤 No Assignment



NOTE: No site sketch detected!
Please be sure to add at least one.

JOB INFORMATION

Site Name	Bridge No.03474
Address	Thompson hill Rd Over Route 395
TRC Project Number	501871.8423.0710
Project Manager	Erik Plimpton, Stephen Arienti, Michael Kostruba
Inspector(s)	Andrew Smith, Alex Lemay
Client	ConnDOT
Type of Asbestos Survey	Reno/Demo
Site Sketch Diagrams	
Additional Analysis for NOB Materials (Calc)	TEM NY NOB 198.4
PLM Turnaround Time (TAT)	3-day
TEM Turnaround Time (TAT)	5-day
Date	March 5, 2025
General Notes	



Overview Photo





Options & Other Settings

Use auto-numbering?	No
Auto-fill gaps?	Yes
Alert user about missing site sketch?	Yes

SURVEYS PERFORMED | Asbestos, XRF, TCLP Sampling

Asbestos Survey

Materials & Samples (7 Items)

Materials & Samples - 1. (2) Samples #1-2: C1-White caulk on south side bridge railings

Sample Information

Asbestos Samples (2 Items)

Asbestos Samples - 1. Sample #1: C1...South side railing

Sample Number	1
Sample Location	South side railing
Asbestos Bulk Analysis	PLM EPA 600/R93/116
Grab or Composite	Grab
Date	March 5, 2025
Time	10:53

Sample Location Photo

Asbestos Samples - 2. Sample #2: C1...South side railing

Sample Number	2
Sample Location	South side railing
Asbestos Bulk Analysis	PLM EPA 600/R93/116
Grab or Composite	Grab
Date	March 5, 2025
Time	10:53

Sample Location Photo



Material Information

Sampled or Assumed?	Sampled
Material Acronym	C ▶ 1
Material Description	White caulk on south side bridge railings
Material Color	White

Representative Photos



Analyze by layer?	No
Is material non-friable organically bound (NOB)?	Yes
Homogeneous Area	
Total Approximate Quantity	
Notes	

Materials & Samples - 2. (2) Samples #3-4: C2-Grey caulk in bridge joints

Sample Information

Asbestos Samples (2 Items)



Asbestos Samples - 1. Sample #3: C2...South side

Sample Number	3
Sample Location	South side
Asbestos Bulk Analysis	PLM EPA 600/R93/116
Grab or Composite	Grab
Date	March 5, 2025
Time	11:08

Sample Location Photo

Asbestos Samples - 2. Sample #4: C2...North side

Sample Number	4
Sample Location	North side
Asbestos Bulk Analysis	PLM EPA 600/R93/116
Grab or Composite	Grab
Date	March 5, 2025
Time	11:08

Sample Location Photo

Material Information

Sampled or Assumed?	Sampled
Material Acronym	C ▶ 2
Material Description	Grey caulk in bridge joints
Material Color	Grey



Representative Photos



Analyze by layer?	No
Is material non-friable organically bound (NOB)?	Yes
Homogeneous Area	
Total Approximate Quantity	
Notes	

Materials & Samples - 3. (2) Samples #5-6: C3-Grey caulk in bridge seams

Sample Information

Asbestos Samples (2 Items)

Asbestos Samples - 1. Sample #5: C3...South side

Sample Number	5
Sample Location	South side
Asbestos Bulk Analysis	PLM EPA 600/R93/116



Grab or Composite	Grab
Date	March 5, 2025
Time	11:03
Sample Location Photo	

Asbestos Samples - 2. Sample #6: C3...North side

Sample Number	6
Sample Location	North side
Asbestos Bulk Analysis	PLM EPA 600/R93/116
Grab or Composite	Grab
Date	March 5, 2025
Time	11:03
Sample Location Photo	

Material Information

Sampled or Assumed?	Sampled
Material Acronym	C ▶ 3
Material Description	Grey caulk in bridge seams
Material Color	Grey



Representative Photos



Analyze by layer?	No
Is material non-friable organically bound (NOB)?	Yes
Homogeneous Area	
Total Approximate Quantity	200 LF
Notes	

Materials & Samples - 4. (2) Samples #7-8: C4-Black caulk around north side railings

Sample Information

Asbestos Samples (2 Items)

Asbestos Samples - 1. Sample #7: C4...North railing

Sample Number	7
Sample Location	North railing
Asbestos Bulk Analysis	PLM EPA 600/R93/116



Grab or Composite	Grab
Date	March 5, 2025
Time	11:18
Sample Location Photo	

Asbestos Samples - 2. Sample #8: C4...North railing


Sample Number	8
Sample Location	North railing
Asbestos Bulk Analysis	PLM EPA 600/R93/116
Grab or Composite	Grab
Date	March 5, 2025
Time	11:18
Sample Location Photo	

Material Information

Sampled or Assumed?	Sampled
Material Acronym	C ▶ 4
Material Description	Black caulk around north side railings
Material Color	Black



Representative Photos



Analyze by layer?	No
Is material non-friable organically bound (NOB)?	Yes
Homogeneous Area	
Total Approximate Quantity	
Notes	

Materials & Samples - 5. (2) Samples #9-10: RT 1-Black road tar

Sample Information

Asbestos Samples (2 Items)

Asbestos Samples - 1. Sample #9: RT 1...Black road tar

Sample Number	9
Sample Location	Black road tar
Asbestos Bulk Analysis	PLM EPA 600/R93/116



Grab or Composite	Grab
Date	March 5, 2025
Time	11:14
Sample Location Photo	

Asbestos Samples - 2. Sample #10: RT 1...Black road tar

Sample Number	10
Sample Location	Black road tar
Asbestos Bulk Analysis	PLM EPA 600/R93/116
Grab or Composite	Grab
Date	March 5, 2025
Time	11:14
Sample Location Photo	

Material Information

Sampled or Assumed?	Sampled
Material Acronym	RT 1
Material Description	Black road tar
Material Color	Black



Representative Photos



Analyze by layer?	No
Is material non-friable organically bound (NOB)?	Yes
Homogeneous Area	
Total Approximate Quantity	
Notes	

Materials & Samples - 6. (2) Samples #11-12: TJF 1-Black Tar joint filler In joints and along curb

Sample Information

Asbestos Samples (2 Items)

Asbestos Samples - 1. Sample #11: TJF 1...South side

Sample Number	11
Sample Location	South side



Asbestos Bulk Analysis	PLM EPA 600/R93/116
Grab or Composite	Grab
Date	March 5, 2025
Time	11:10

Sample Location Photo

Asbestos Samples - 2. Sample #12: TJF 1...North side

Sample Number	12
Sample Location	North side
Asbestos Bulk Analysis	PLM EPA 600/R93/116
Grab or Composite	Grab
Date	March 5, 2025
Time	11:11

Sample Location Photo

Material Information

Sampled or Assumed?	Sampled
Material Acronym	TJF 1
Material Description	Black Tar joint filler In joints and along curb
Material Color	Black



Representative Photos



Analyze by layer?	No
Is material non-friable organically bound (NOB)?	Yes
Homogeneous Area	
Total Approximate Quantity	
Notes	

Materials & Samples - 7. (2) Samples #13–14: RG 1–Tan rope gasket around bearing bases

Sample Information

Asbestos Samples (2 Items)

Asbestos Samples - 1. Sample #13: RG 1...Bearing under bridge

Sample Number	13
Sample Location	Bearing under bridge
Asbestos Bulk Analysis	PLM EPA 600/R93/116



Grab or Composite	Grab
Date	March 5, 2025
Time	11:38
Sample Location Photo	

Asbestos Samples - 2. Sample #14: RG 1...Bearing under bridge

Sample Number	14
Sample Location	Bearing under bridge
Asbestos Bulk Analysis	PLM EPA 600/R93/116
Grab or Composite	Grab
Date	March 5, 2025
Time	11:38
Sample Location Photo	

Material Information

Sampled or Assumed?	Sampled
Material Acronym	RG 1
Material Description	Tan rope gasket around bearing bases
Material Color	Tan
Representative Photos	
Analyze by layer?	No
Is material non-friable organically bound (NOB)?	No
Homogeneous Area	
Total Approximate Quantity	
Notes	

XRF Survey

Niton XRF Model No.	24792
XRF Survey Completed	Yes
XRF Data Downloaded	Yes
XRF Shots >1.0 on non-metallic building materials	No
Date Data Downloaded	March 5, 2025



TCLP/SPLP/Total Lead Survey

Samples (2 Items)

Samples - 1. Grey railing paint

TCLP/SPLP/Total Lead Sample Description	Grey railing paint
---	--------------------

TCLP/SPLP/Total Lead Components

Type of Analysis	TCLP Lead
Sample Number	1
Grab or Composite	Grab
Date	March 5, 2025
Time	11:28
TCLP/SPLP/Total Lead Notes	
TCLP/SPLP/Total Lead Photos	

Samples - 2. Grey paint on support beams.

TCLP/SPLP/Total Lead Sample Description	Grey paint on support beams.
---	------------------------------

TCLP/SPLP/Total Lead Components

Type of Analysis	TCLP Lead
Sample Number	2
Grab or Composite	Grab
Date	March 5, 2025
Time	11:45
TCLP/SPLP/Total Lead Notes	
TCLP/SPLP/Total Lead Photos	

LAB & SAMPLE SUBMISSION INFO

Signature	
-----------	--



Asbestos Bulk Samples

Remarks to be added to the CoC

Asbestos samples submitted to TRC lab? No

Date Submitted to Lab

Asbestos bulk sample CoC data electronically sent to lab yet? No

Asbestos bulk sample results reviewed? No

TCLP Samples

TCLP/SPLP Samples Submitted to Lab No

TCLP/SPLP Samples Submitted To:

Date Submitted to Lab

REPORT CREATION

Select one or more documents below to be generated. Once completed in the cloud, they will be sent to the listed email address.

NOTE: Asbestos bulk sample CoC data must now be sent electronically to the lab by selecting "Asbestos chain-of-custody - Send to Lab" from the list below.

What documents should be generated?

Generate Documents

PROJECT STATUS TRACKING

Has this survey been completed? Yes

Has the report been written? No

Has the report been reviewed? No

