Hazen

Appendix A: Existing Conditions Photos

Hazen

High Tide



Figure 1 High Tide South Wall



Figure 2 High Tide Corner of South and East Walls Settlement



Figure 3 High Tide Corner of South and East Walls Settlement



Figure 4 High Tide Corner of South and East Walls 12-in grout loss




Figure 5 High Tide South Wall 22-in grout loss



Figure 6 High Tide East Wall 9-in grout loss



Figure 7 High Tide East Wall 17-in grout loss



Figure 8 High Tide East Wall Closeup

Low Tide



Figure 9 Low Tide Bridge Waterway



Figure 10 Low Tide South Wall



Figure 11 Low Tide East Wall



Figure 12 Low Tide East Wall - Near boat launch area



Figure 13 Low Tide Corner of South and East Walls



Figure 14 Low Tide Corner of South and East Walls Void 36-in depth



Figure 15 Low Tide South Wall near Corner of South and East Walls 30-in grout loss




Figure 16 Low Tide East Wall 7-in grout loss near fence



Figure 17 East Wall 20-in grout loss near Corner of South and East Walls