

CITY/TOWN MARION=WAREHAM	B.I.N. 45E	BR. DEPT. NO. M-05-001=W-06-013	8.-STRUCTURE NO. M05001-45E-DOT-NBI	INSPECTION DATE OCT 12, 2016
-----------------------------	---------------	------------------------------------	--	---------------------------------

PHOTOS

Photo 13: Tee Bay 5 at west abutment, area of 100% section loss to unused utility conduit



Photo 14: Span 1 Tee Beam 1 looking east, spalling w/ exposed rebar