

CITY/TOWN
WAREHAMB.I.N.
45KBR. DEPT. NO.
W-06-0168.-STRUCTURE NO.
W06016-45K-DOT-NBIINSPECTION DATE
OCT 12, 2016

PHOTOS



Photo 35: Same utilities as previous photo, span 3 at east abutment. Utility pipe on right with a hole, apparently abandoned



Photo 36: Overview of west approach pavement and sawcut joint. East approach pavement and sawcut joint is similar